

Revised/Partially rebuilt 3 yrs ago. No previous dwelling was rubble stone construction but with a clay/mud wall with only a few stones on the first story front elevation. The "back" house was built of brick.

AM 13 to Dec. 1985

The Owner has photographs of the house before & during renovation work.

Old House before rebuilding Addition ~ 1900

