

Chapel seen whilst driving past.

Stone built, disused, slate roof partly missing. Within high walled enclosure.

Entrance porch with mock-norman arch.

Arched window with brick surround.

Inside fixtures: wooden paneling, wooden benches, floor is wooden, partly rotten.

Inscription painted on wall:

Dyrchafun Ein Sanctaidd Ywr

Galennau at DDuw Arglwydd Ein Ddw

AM 30/4/85.

