

farmhouse and byre/stables:

Stone built. Hse. Thatched roof now covered with corrugated iron.

Barn roof slated. A section of the front wall of the house has collapsed & the roof here has fallen in.

Cobbled area in front of the barn.

Enclosure wall visible to the back of the farmstead (N).

Er Evans Dec 1983

