


COMMENT

AUTHORITY



Derelict for last 3 years: now FC property
Barn & old farmhouse: roofs thatched
but covered over with corrugated
iron. Latest dwelling: modern.
Enclosure wall.

Ellewaas Dec 1983