

## **The Old Library, Corporation Street, Aberystwyth.**

### **Pre Start Photographic record of the building.**

Planning Consent Ref A211032

#### **Condition 4.**

The development shall not begin until an appropriate photographic survey of the existing building(s) has been carried out in accordance with guidelines provided by the Local Planning Authority's archaeological advisors - Dyfed Archaeological Trust-Heritage Management. The resulting photographs should be approved by the planning authority prior to the commencement of development and deposited with the regional Historic Environment Record held, and maintained by the Dyfed Archaeological Trust, Corner House, Carmarthen Street, Llandeilo, Carmarthenshire, SA19 6AE, (Tel 01558-823121).

Photo 1 External Corporation St Elevation.



Photo 2 Corporation Street Entrance



Photo 3 Corporation Street Ground Floor Windows





Photo 4 Front Elevation Granite Plaque



Photo 5 Rear yard





Photo 6 South Elevation



Photo 7 North Elevation Existing Upvc Windows



Photo 8 North Elevation Showing Polycarbonate Roofing.



Photo 9 Steps up from entrance



Photo 10 Looking back at entrance





Photo 11 Internal view of North Wall.



Photo 12 Tiling on North Wall.



Photo 13 Front Stair (Concrete)



Photo 14 Rear Stair (Timber)



Photo 15 Rear Stair (Timber Detail)



Photo 16 Rear Stair rain water pipe.





Photo 17 First Floor Landing Rear Stair.



Photo 18 Ground Floor view towards West.





Photo 19 Ground Floor Damage to Parquet Flooring



Photo 20 Ground Floor view towards South West.



Photo 21 View of shelving on South Wall.



Photo 22 View towards South East corner.





Photo 23 View towards North East Corner



Photo 24 Room in North West Corner of Ground Floor



Photo 25 Room in South West Corner of Ground Floor.



Photo 26 Bathroom on top mezzanine North East Corner.





Photo 27 First Floor View Towards East



Photo 28 First Floor View Towards North.



Photo 29 First Floor View Towards West.



Photo 30 First Floor View Out Of Window Towards North West.






Photo 31 First Floor Dry Rot in Floor Boards



Photo 32 First Floor South Wall and Ceiling

