

# Heritage

Recording Services Wales

## Gilfach-y-berthog, Abergwilli, Carmarthenshire.

### Archaeological Watching Brief



*By*

Richard Scott Jones (*MA, MIFA*)

October 2013

HRSWales  
Report No: 131



# ARCHAEOLOGICAL WATCHING BRIEF

## Gilfach-y-berthog, Abergwilli, Carmarthenshire.

By

Richard Scott Jones (*BA Hons, MA, MIFA*)

*Prepared for:*

Davies Sutton Architects  
Penhevad Studios  
Penhevad Street  
Grangetown  
Cardiff  
CF11 7LU

*On behalf of:*

*Date:* October 2013

HRSW Report No: 1311

**Heritage**  
Recording Services Wales

Pen-y-Fan, 11 Forest Lane, Llangybi, Ceredigion, SA48 8LZ

Tel: 01570 493312 Fax: 08712 428171 E-mail: [richard@hrswales.co.uk](mailto:richard@hrswales.co.uk)



## **Contents**

### *i) List of Illustrations and Photo plates*

<b>Non Technical Summary</b>	<b>Page i</b>
<b>1. Introduction</b>	<b>Page 01</b>
<b>2. Aims &amp; Objectives</b>	<b>Page 03</b>
<b>3. Methodology</b>	<b>Page 03</b>
<b>4. Results of Watching Brief</b>	<b>Page 10</b>
<b>5. Conclusions &amp; Recommendations</b>	<b>Page 11</b>
<b>6. Acknowledgements</b>	<b>Page 13</b>
<b>7. Bibliography &amp; References</b>	<b>Page 13</b>

**Appendix I: Figures**

**Appendix II: Photo plates**


**Appendix III: Contexts Register**

**Appendix IV Levels Register**

**Appendix V: Archive Cover Sheet**

### **Copyright Notice:**

*Heritage Recording Services Wales retain copyright of this report under the Copyright, Designs and Patents Act, 1988, and have granted a licence to Davies Sutton Architects to use and reproduce the material contained within.*




## **i) List of Illustrations**

### *Figures*

- Fig 01: Location map
- Fig 02: Aerial photo
- Fig 03: General site plan
- Fig 04: Proposed general site plan
- Fig 05: House floor plans
- Fig 06: Existing external elevations
- Fig 07: Ground plan of Lower Parlour
- Fig 08: General site plan and trench location
- Fig 09: Ground plan of kitchen extension
- Fig 10: Lower Parlour Room ground plan - Early 17th century cobbled floor
- Fig 11: Lower Parlour Room ground plan - Early 17th century culverts
- Fig 12: Kitchen extension ground plan
- Fig 13: Ground plan showing Trench 1 and Service trench 1
- Fig 14: Trench 1 - Section A-B
- Fig 15: Ground plan of Service trench 2
- Fig 16: Ground plan of Service trench 3
- Fig 17: Ground plan and section of Service trench 4
- Fig 18: Ground plan showing results from Service trench 4
- Fig 19: Ordnance Survey 1:2500 maps (1889 and 1906)

### *Plates*

- Plates 01-12: External views of house
- Plates 13-42: General interior views of house
- Plates 43-44: Concrete base and step removal in Service trench 1
- Plates 45-46: Rear of house
- Plates 47-73: Lower Parlour Room - results of ground reduction work
- Plates 74-75: Trenches in stone barn
- Plates 76-86: Kitchen demolition and extension
- Plates 87-95: Service trenches





## Non Technical Summary

*The following report presents the results of a programme of archaeological works undertaken at the Grade II\* Listed 18<sup>th</sup> century welsh gentry house of Gilfach-y-Berthog, Abergwilli, Carmarthenshire, during proposed restoration and renovation works of the main house and stable, both Grade II Listed Buildings. It details the results of an archaeological watching brief undertaken during ground reduction works in the Lower Parlour Room in the main house, during the demolition of the early 20<sup>th</sup> century kitchen extension attached to the east of the house, groundwork during the excavation for a series of pier supports in one of the outbuildings, and the ensuing ground reduction works for the proposed new kitchen extension, and a watching brief during groundwork for a number of service trenches within the farmstead complex.*

*In summary, the ground reduction work in the Lower Parlour Room of the main house exposed the remains of an early 17<sup>th</sup> century cobbled floor with extensive repair at its eastern end. Following full recording of this exposed floor, initial removal of the apparent repair work exposed the remains of a small 19<sup>th</sup> century slack lime processing pit, with structural evidence suggesting that the feature may have had some kind of chimney flue arrangement that took generated smoke and fumes to the outside through a hole in the north wall alongside the 17<sup>th</sup> century inglenook fireplace. Again, following full recording of this structure and the complete removal of the damaged cobbled floor, a network of stone cut drainage culvert channels became exposed, entirely covered by a series of stone capstones. Inspection revealed that this complex of culverts once took excessive run-off water away from the rear of the house and guided it beneath the house foundations to the south of the property, where upon it would have once travelled to a large pond at the far south-western end of the farmstead complex. Removal of a number of capping stones from the culvert channels showed that much of the culvert was blocked from silt. This work managed to recover the remains of several fragments of early 17<sup>th</sup> pottery sherds. No pottery remains encountered from this groundwork were earlier than this date.*

*The watching brief during the demolition of the early 20<sup>th</sup> century red brick kitchen extension revealed that the extension had been built directly onto the natural shale bedrock. No finds earlier than the early 20<sup>th</sup> century were recovered from the demolition work. Following demolition of the 20<sup>th</sup> century kitchen extension and the full exposure of the east facing elevation, the only architectural feature that became exposed was the position of a former first floor window positioned directly above the ground floor doorway.*

*With regard the watching brief during the ground work for the pier supports in the western barn, southwest of the main house, this work exposed a cobbled surface in each trench. The earliest finds recovered from one of these trenches were all pottery fragments and all were dateable to the 17<sup>th</sup> century, suggesting that the cobbled surface is probably contemporary to the cobbled floor exposed in the main house in the lower parlour room.*

*Regarding the ground work for the service trenches at the rear, side and front of the property, the watching brief found no archaeological finds, features or deposits of any significance.*



## 1 Introduction

- 1.1 The following report presents the results of a programme of archaeological works undertaken at the Grade II\* Listed 18<sup>th</sup> century welsh gentry house of Gilfach-y-Berthog, Abergwilli, Carmarthenshire, during proposed restoration and renovation works of the main house and stable, both Grade II Listed Buildings. It details the results of an archaeological watching brief undertaken during ground reduction works in the Lower Parlour Room in the main house, during the demolition of the early 20<sup>th</sup> century kitchen extension attached to the east of the house, groundwork during the excavation for a series of pier supports in one of the outbuildings, and the ensuing ground reduction works for the proposed new kitchen extension, and a watching brief during groundwork for a number of service trenches within the farmstead complex.

### Site Location and Description

- 1.2 The farmstead of Gilfach-y-Berthog is located approximately 5.5km east of Carmarthen town and approximately 1km northwest of the village of Nantgaredig, within the community of Abergwilli in Carmarthenshire (National Grid Reference: SN4813022955). The farmstead consists of a 17<sup>th</sup> century minor gentry *mansion* house (Grade II\* Listed), an associated 17<sup>th</sup> century barn/byre building (Grade II Listed), a 19<sup>th</sup> century stone barn and other outbuildings.

### Planning Background & Development Proposals

- 1.3 Following submission of a planning application (Ref: W/23376) detailing the development proposals at Gilfach-y-Berthog, to Carmarthenshire County Council (henceforth CCC) on 29<sup>th</sup> October 2010, full planning permission was granted by CCC, with condition 5 stipulating that,

"No development shall take place until the applicant, or their successors in title, has secured the implementation of a programme of archaeological work in accordance with a written scheme of investigation which has been submitted by the applicant and approved in writing by the Local Planning Authority. The development shall be carried out in accordance with the approved scheme".

- 1.4 As part of the planning application, listed building consent was also granted by CCC for the demolition of the extension to the stable barn and its replacement with a timber clad barn extension (LBC Ref: W/24022). The restoration and extension of the main house was granted separate listed building consent (LBC Ref: W/24008).
- 1.5 It had been agreed during discussions with the local planning authority that specialist interpretative building survey information was not required. A comprehensive recording of the standing buildings had been provided by *Davies Sutton Architects* to the local authority. This was to be confirmed as acceptable by the local planning authority prior to being deposited with the RCAHMS.
- 1.6 Development proposals aimed to:
- restore the Grade II Listed house
  - to demolish an existing lean-to kitchen extension and replace with a modern vernacular kitchen extension
  - demolish a modern brickwork extension to the stable barn and replace with a timber clad barn extension



- carry out landscaping

1.7 It is anticipated that an archaeological watching brief will be undertaken during the following works:

- ground excavations to the proposed kitchen extension
- lifting of floor and excavation in existing basement to existing house
- external excavations to enable waterproofing to the rear of the house
- service and drainage trenches
- trial holes and excavations for pad foundations to the timber clad barn extension.

### **Brief Historical & Archaeological Background**

1.8 The existing main house of Gilfach-y-Berthog (PRN: 11095) is a late seventeenth century minor gentry house of 'T' shaped plan. It is a stone-built building, two and a half storeys high with an end-chimney. The RCAHMW database entry for the house describes the house thus:

*"The house consists of a central entry and passage with flanking main rooms and open well stair in rear wing, which has earlier ceiling-beams to kitchen. The parlour retains a finely plastered ceiling, a fireplace with pillasters to an overmantel and a 1692 date inscription within oval strapwork. This strap-work is echoed in a similar vein in the external stucco decoration. The room over the parlour has a high quality plaster moulded chimney piece with ionic columns of same period. The first-floor front rooms retain original 2-light timber mullion and transom windows. They have 'ogee' internal mouldings, formerly with leaded glazing. There are some simple 2-light windows at landing in rear wing" (RCAHMW database entry NPRN: 17364).*

- 1.9 The associated Grade II Listed barn and byre building (PRN: 25466) is a 17<sup>th</sup> century stone built threshing barn with opposed cart entries. It features three pairs of scarfed crucks that could be contemporary with the house. The north gable wall differs from the side walls, though all are stone rubble, and it is possible that the sides were originally timber framed. The south end of the building was the byre or cow house (RCAHMW database entry NPRN: 31600).
- 1.10 The associated Grade II Listed 19<sup>th</sup> century stone built stable is a single storey lofted building with limewashed rubble walls and a slate roof (NPRN: 31601).
- 1.11 The farmstead of Gilfach-y-Berthog is described in Francis Jones' 'Historic Carmarthenshire Homes and their families' (1987), with further mention of the site in 12<sup>th</sup> century manuscripts.
- 1.12 On 23<sup>rd</sup> April 2011 Dyfed Archaeological Trust (Field Services), observed the excavation of a series of 5 geo-technical test pits in the area of the main house, ahead of proposals for the construction of a swimming pool. The archaeological presence on site was to observe whether any archaeological features, finds or deposits may become exposed, damaged or destroyed by the proposed development. Dyfed Archaeological Trust's subsequent report (DAT Ref: FS10-008-JM-170510) concluded that, "No archaeological deposits were recorded in any of the five test pits. The majority of trenches comprised topsoil directly overlying the natural bedrock.....The results indicate that further archaeological investigation would be unnecessary, as it is considered that the swimming pool would have no impact on any buried archaeological resource. If any such remains



had existed prior to the house being constructed, they would have been destroyed when the ground was terraced. No indication of any archaeological remains associated with the house, other than garden soils and terracing, was observed" (DAT Report ref: FS10-008-JM-170510 - 23/04/11).

## **2 Aims & Objectives**

2.1 The aims of the watching brief, as defined by the IfA (2001) are:

- To allow a rapid investigation and recording of any archaeological features that are uncovered during the proposed groundwork.
- To provide the opportunity, if needed, for the watching archaeologist to signal to all interested parties, before the destruction of the material in question, that an archaeological find has been made for which the resources allocated to the watching brief are not sufficient to support the treatment to a satisfactory or proper standard.

## **3 Methodology**

- 3.1 The archaeological watching brief was undertaken by HRS Wales staff using current best practice from January 2012.
- 3.2 All work was carried out by a suitably qualified archaeologist with relevant level membership of the Institute for Archaeologists (IfA) and followed the IfA Standard and Guidance for an archaeological watching brief (IfA 2001).
- 3.3 All proposed groundwork was undertaken under close and constant archaeological supervision.
- 3.4 All archaeological deposits or features encountered were cleaned, recorded and excavated. When external render and internal plasterwork was removed from elevations, then the exposed fabric was inspected and any exposed features were photographically recorded.
- 3.5 Recording was carried out using HRS Wales recording systems (pro-forma context sheets etc), using a continuous number sequence for all contexts.
- 3.6 Plans and sections were drawn to a scale of 1:50, 1:20 and 1:10 as required and related to Ordnance Survey datum and published boundaries where appropriate.
- 3.7 All features identified were tied in to the both the OS National Grid and all local site and ground plans.
- 3.8 Photographs were appropriated in digital format, using both a 10 mega-pixel Olympus DSLR camera and a 14 mega-pixel Canon Powershot G10, with photographs stored in both RAW and JPEG formats.

## **4 Results of Watching Brief**

- 4.1 All numbers in brackets (), refer to archaeological contexts encountered during the watching brief.






### *General Description*

- 4.2 Archaeological work included a watching brief during ground reduction work in the Lower Parlour Room of the main house, the demolition of the existing Kitchen extension and ground reduction work at the east end of the house, ground work for the cutting of a series of six pier supports in the barn building to the west of the complex, and a watching brief during the cutting of a series of new services trenches.

#### *Lower Parlour Room (see Figures 10 and 11; Photo plates 49-73)*

- 4.3 The Lower Parlour Room is located at the northern end of the ground floor off the main house. It can be accessed either from the former front door of the earlier 17<sup>th</sup> century house, or via a series of steps down from the main ground floor hallway in the late 17<sup>th</sup> century part of the house. This room is characterised by exposed timber ceiling and a large inglenook fireplace in the north wall, complete with a former bread oven within each side wall.
- 4.4 Proposed groundwork in this room entailed the reduction of the floor level by approximately 0.30m to install modern under-floor heating.
- 4.5 At the time of the watching brief the entire floor of the Lower Parlour Room was surfaced in large modern stone floor tiles (100). All of these stone tiles were lifted and removed from the room. These stone tiles had been bedded onto a mixture of sand and pea-grit (101), which averaged approximately 0.20m in depth. Directly below this was a polyurethane plastic membrane (102). Directly below this membrane was a stone and earth levelling deposit (103), which averaged approximately 0.10m in depth. Once this loose deposit was removed, a pitched or cobbled floor became exposed (104). This floor was composed of river cobbles of various sizes, from 0.05 – 0.20m in size. This cobbled surface covered approximately 70% of the lower parlour room floor, with areas alongside both doorways at the west end of the room being absent of any cobbles, suggesting that these areas probably once held large slate slabs, since robbed or removed prior to the covering of floor in the later centuries. There was also evidence of major cobbled floor repair at the east end of the room, with areas of former cobbles having been replaced with fragments of black slate and red brick. Further damage to the cobbled floor was evident in the centre of the room, where the insertion of a 20<sup>th</sup> century electric cable had once dug a cut (108).
- 4.6 Once the overlying levelling deposit (103) had been completely removed from the cobbled floor (104), the exposed surface was cleaned by trowel and eventually brushed in order that the exposed floor could be recorded photographically and recorded in plan. During this cleaning process no finds earlier than the 19<sup>th</sup> century were recovered.
- 4.7 Once this recording work had been completed, because the cobbled floor had been significantly damaged in many areas in the past, the remaining cobbles were lifted in order that the proposed ground reduction work could continue to the required proposed level. However, prior to the cobbles being removed, it was decided that initially the areas of the floor that had seen significant repair work were investigated by removing the areas of repair.
- 4.8 At the far east end of the room, the removal of a large outline of red brick, black slate and other stones, which were not river cobbles, exposed the remains of a former slaked lime processing pit (106). This feature obviously post-dated the cobbled surface as its original construction had caused the removal of part of the cobbled floor.



Remnants of slaked lime in the pit were identical to the remains of slaked lime that was found at the base of the east, north and southern walls (107), overlying the cobbled surface. This suggested that the processing pit had probably been constructed for the production of slaked lime for building use as well as to coat the interior walls of parts of the house in either the late 17<sup>th</sup> century or the 18<sup>th</sup> century.

- 4.9 Careful excavation of the lime pit revealed that it had been constructed by digging a shallow 'kidney' shaped hole through the cobbled surface, with a small rectangular structure of red brickwork, only one course high remaining, forming an apparent hearth and flue at its northern end. These remaining bricks had no makers stamps on them and had been mortared together with lime mortar. Their character and fabric suggested that they were either 18<sup>th</sup> century or early 19<sup>th</sup> century in date.
- 4.10 Once the surface parts of this feature had been fully exposed and recorded, the lifting and removal of the cobbled floor (104) continued across the entire floor area. Lifting of the remaining cobbled floor revealed that the cobbles had been bedded into a deposit of dark earth and small stones (109). This deposit averaged approximately 0.05m – 0.10m in depth. Dateable material recovered from this cobble bedding deposit included several fragments of 17<sup>th</sup> century Glazed Dyfed Gravel Tempered ware.
- 4.11 Complete removal of the underlying cobbled bedding deposit (109) from the entire room exposed a network of stone capped rain drainage culverts (110). In total, three main culvert channels became exposed, each meeting approximately in the centre of the room at a junction channel. From here this culvert continued southwards towards the internal doorway that leads to the small basement/cellar part of the house. Further investigation of these culvert channels revealed that the main channels entered the house from beneath the north wall, one to the east, one to the west and one central to the room within the base of the inglenook fireplace. Each of these channels had been deliberately cut into the natural bedrock (111) to divert run-off rain water away from the rear of the house. In order to try and date the construction of these culvert channels, a number of culvert capping slabs were lifted, in the hope that some dateable material could be recovered from inside the channels themselves. The lifting of these capping stones revealed that none of the channels were silted up to the point of being blocked, but were fairly clear. Dateable material, in the form of pottery fragments, recovered from the base of the culverts in the inspected areas, were all early 17<sup>th</sup> century in date. This would suggest that the cutting of the culverts, the cobbled surface and very likely this part of the house is early 17<sup>th</sup> century in date and no earlier.
- 4.12 Once the layout of the culvert channels had been photographed and recorded in plan, further inspection was made of the slaked lime processing pit (106), which had been left in situ in order to fully record its character.

#### *Slaked Lime processing Pit*

- 4.13 Natural Lime is calcium oxide. The word lime originates with its earliest use as building mortar and has the sense of 'sticking or adhering'. When lime is crushed up and then heated and burnt in a lime kiln, it converts into a highly caustic material, known as quicklime. When water is added to this quicklime the product becomes less caustic and becomes calcium hydroxide, otherwise known as slaked lime. This process is called slaking of lime. Slaked lime is mixed into thick slurry with sand and water to form various kinds of mortar and render for building purposes. Also often made was lime putty used in the creation of stucco and fresco work.
- 4.14 Further investigation of the slaked lime pit in the lower parlour room, following the



removal of the cobbled floor and its associated bedding deposit from around the feature, revealed that the red brick structure at the northern end of the pit had remnants of soot and charcoal at the base of its internal opening, implying that this part of the structure was most probably used as a stoke hole or a grate to collect burnt ashes from a fire that had been lit from above in another now absent structure, perhaps even a very small lime kiln. Fumes from this burning were probably extracted from the room through a chimney flue arrangement that had once been punctured through a hole in part of the north wall alongside the eastern side of the inglenook fireplace.

- 4.15 Following removal of plasterwork from this wall as part of the restoration proposals, thus exposing the fabric, revealed that there had indeed once been an opening here, which had since been blocked in. This former opening would help explain the presence of an apparent stone built and roofed bread oven built against the external north wall at the rear of the house. This 'oven' likely made use of the already existing 'hole' in this wall.
- 4.16 Another interesting feature of the slaked lime processing pit, was the fact that the shallow end of the slaked lime collecting basin, at the northern end directly adjacent to the red brick structure, appeared to lead into a gap between two of the culvert capping stones on which the feature rested, which suggested that some slaked lime slurry or lime water may have been deliberately expelled down the culvert. If this was the case then it may suggest that there had originally been some kind of small sluice between the basin and the red brick stoke hole, to allow excess lime water to be expelled easily during the cleaning of the basin following the end of any processing.
- 4.17 One puzzling question still remains however, why was this lime processing undertaken inside the house and not outside?
- 4.18 One answer to this question may be that, given that the feature most certainly does appear to have been used for the creation of slaked lime, keeping the initial powdered lime dry would have been crucial to the first stage of processing and the creation of slaked lime would have had to have been a carefully monitored process in order to create the perfect product required for building purposes.
- 4.19 So, given that the southern part of Gilfach-y-berthog house had become the main living area in the late 17<sup>th</sup> century, the lower parlour room had now become less important in terms of social display and had become more of a domestic space, a kitchen area, which was conveniently close to the proposed building area and also offered shelter from the welsh rain.
- 4.20 This above interpretation does however suggest that the slaked lime pit was constructed in the late 17<sup>th</sup> century as part of the building work for the late 17<sup>th</sup> century house. However, the bricks used in the brick stoking structure of the lime pit suggest that the feature is early to mid 18<sup>th</sup> century in date. This would imply that the slaked lime pit was constructed for later building purposes during 18<sup>th</sup> century improvements and not late 17<sup>th</sup> century ones.
- 4.21 Also, the manner in which the pit was covered over again with only a hap-hazard repair of the cobbles using black slate and red brick suggests that there was little concern about the appearance of the repaired cobbled floor in this room at this time.



*Kitchen Demolition and New Extension (see Figs 12, 14; Photos 6, 7, 10, 25-30 & 76-84)*

- 4.22 Prior to the demolition work of the existing kitchen extension built against the northeast wall of the house, a photographic record was made of both the exterior and interior.
- 4.23 The kitchen extension appears to be mid-late 19<sup>th</sup> century in construction, built of red brick with cement and sandstone rendered window frames. All existing windows are later 20<sup>th</sup> century in date. With regards to the kitchen interior, at the time of the site visit, apart from a 1950s Rayburn range built into the north wall, all other fixtures and fittings were modern in date.
- 4.24 The floor surface of the existing kitchen was constructed from 6 inch square quarry tiles, each laid at a diagonal across the entire floor.
- 4.25 Complete demolition and lifting of the quarry tiled floor revealed that the foundations had been built directly onto the natural bedrock (114). With the quarry tiled floor removed, no dateable finds earlier than the 19<sup>th</sup> century were recovered.
- 4.26 With regards to the investigation of the exposed standing fabric, a feature of interest that became exposed was a former window opening in the east facing wall of the earlier early 17<sup>th</sup> century house at first floor level, which was unblocked and had once given light into the roofing space of the former kitchen extension.
- 4.27 Another exposed feature was an apparent line in the plasterwork and fabric in both the newly exposed east and north facing walls, that appeared to mark the position of an earlier but lower building extension, perhaps a slightly earlier kitchen extension or lean-to building.
- 4.28 Other features exposed were the position of several put-logs in both the north and east facing walls.
- 4.29 The cutting of the ground for the new kitchen extension, which was to now extend much further eastwards, revealed that the overlying top soil and sub soil contained 19<sup>th</sup> century material only. Directly below these 20<sup>th</sup> century deposits, the groundwork exposed natural shale bedrock (114), suggesting that this area had already been heavily landscaped and disturbed in more recent years.

*Pier Supports in western Barn*

- 4.30 In order that a new garage had been proposed as part of the proposed development, an existing unlisted building at the west end of the complex was demolished and the excavation of 6 small trenches through a modern concrete floor was necessary to install six new concrete pier supports. Each of these trenches was to be measure approximately 0.50m x 0.50m.
- 4.31 The cutting of each of these small trenches through modern concrete revealed that the concrete was only approximately 0.10m-0.15m in depth (115). This concrete base had been laid over a sub base of earth, stone and sand (116). This averaged approximately 0.20m in depth in each trench. Directly below this sub base was a dark earth deposit intermixed with ash and soot, approximately 0.05m in depth (117). Directly below this deposit, in three of the trenches, No's 1, 2 and 4, excavation exposed a cobbled floor, similar to that already exposed in the Lower Parlour Room of

1990 1991 1992 1993

1994 1995 1996 1997 1998 1999 2000

2001 2002 2003 2004 2005 2006 2007

2008 2009 2010 2011 2012 2013 2014 2015 2016 2017 2018 2019 2020

2021 2022 2023 2024 2025 2026 2027 2028 2029 2030

2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050

2051 2052 2053 2054 2055 2056 2057 2058 2059 2060 2061 2062 2063 2064 2065 2066 2067 2068 2069 2070 2071 2072 2073 2074 2075 2076 2077 2078 2079 2080 2081 2082 2083 2084 2085 2086 2087 2088 2089 2090 2091 2092 2093 2094 2095 2096 2097 2098 2099 2100

2101 2102 2103 2104 2105 2106 2107 2108 2109 2110 2111 2112 2113 2114 2115 2116 2117 2118 2119 2120 2121 2122 2123 2124 2125 2126 2127 2128 2129 2130 2131 2132 2133 2134 2135 2136 2137 2138 2139 2140 2141 2142 2143 2144 2145 2146 2147 2148 2149 2150

2151 2152 2153 2154 2155 2156 2157 2158 2159 2160 2161 2162 2163 2164 2165 2166 2167 2168 2169 2170 2171 2172 2173 2174 2175 2176 2177 2178 2179 2180 2181 2182 2183 2184 2185 2186 2187 2188 2189 2190 2191 2192 2193 2194 2195 2196 2197 2198 2199 2200

2201 2202 2203 2204 2205 2206 2207 2208 2209 2210 2211 2212 2213 2214 2215 2216 2217 2218 2219 2220 2221 2222 2223 2224 2225 2226 2227 2228 2229 2230 2231 2232 2233 2234 2235 2236 2237 2238 2239 2240 2241 2242 2243 2244 2245 2246 2247 2248 2249 2250

2251 2252 2253 2254 2255 2256 2257 2258 2259 2260 2261 2262 2263 2264 2265 2266 2267 2268 2269 2270 2271 2272 2273 2274 2275 2276 2277 2278 2279 2280 2281 2282 2283 2284 2285 2286 2287 2288 2289 2290 2291 2292 2293 2294 2295 2296 2297 2298 2299 2300

2301 2302 2303 2304 2305 2306 2307 2308 2309 2310 2311 2312 2313 2314 2315 2316 2317 2318 2319 2320 2321 2322 2323 2324 2325 2326 2327 2328 2329 2330 2331 2332 2333 2334 2335 2336 2337 2338 2339 2340 2341 2342 2343 2344 2345 2346 2347 2348 2349 2350

2351 2352 2353 2354 2355 2356 2357 2358 2359 2360 2361 2362 2363 2364 2365 2366 2367 2368 2369 2370 2371 2372 2373 2374 2375 2376 2377 2378 2379 2380 2381 2382 2383 2384 2385 2386 2387 2388 2389 2390 2391 2392 2393 2394 2395 2396 2397 2398 2399 2400

2401 2402 2403 2404 2405 2406 2407 2408 2409 2410 2411 2412 2413 2414 2415 2416 2417 2418 2419 2420 2421 2422 2423 2424 2425 2426 2427 2428 2429 2430 2431 2432 2433 2434 2435 2436 2437 2438 2439 2440 2441 2442 2443 2444 2445 2446 2447 2448 2449 2450 2451 2452 2453 2454 2455 2456 2457 2458 2459 2460 2461 2462 2463 2464 2465 2466 2467 2468 2469 2470 2471 2472 2473 2474 2475 2476 2477 2478 2479 2480 2481 2482 2483 2484 2485 2486 2487 2488 2489 2490 2491 2492 2493 2494 2495 2496 2497 2498 2499 2500



the main house, suggesting that it was at the latest early 17<sup>th</sup> century in date.

- 4.32 With regards to the other trenches, the area of the trench for support pier No. 3 had already been disturbed from a modern brick built feature. No cobbled surface was exposed in this trench and the ground work down to the required level only exposed the natural bedrock here (119). Both trenches 5 and 6 were positioned at the edge of the modern concrete floor at its eastern end. The trenches for each of these pier supports exposed the natural shale bedrock only (119).

#### *Service Trenches*

- 4.33 Service trenches within the complex had been proposed in five main areas:

- i) ST1 – service trench at the rear of the house at the far north end in order to redirect water run-off away from the main house.
- ii) ST2 – service trench at the eastern side of the house in the area of the new kitchen extension
- iii) ST3 – service trench at the front of the house where a foul drain and a new inspection cover had been proposed.
- iv) ST4 – service trench from front of house running southwards toward the main sewer which lay in the field north of the farm complex.
- v) ST5 – series of service trenches in courtyard area between stone barn and west of main house.

- 4.34 The results from the watching brief during the cutting of each of these service trench areas is given below in the order listed above.

#### *i) ST1 - Service trench at rear of house*

- 4.35 This trench was positioned at the rear of the house at the northern end. Proposals were to reduce the ground at the rear of the house in order to lay a series of drainage pipes to help direct water away from the house, which was suffering fairly severely from rain water that was running off the slope at the rear of the house and causing flooding, which was being detrimental to the foundations.

- 4.36 At the time of the ground work, the existing ground at the rear of the house was modern concrete (120), which had been acting as a base for an oil tank and boiler house. At the north-western corner a small flight of concrete steps (121) allowed access to and from the rear of the house from the western side entrance of the house (the original entrance to the early 17<sup>th</sup> century house).

- 4.37 Following the complete removal of the concrete and steps (120 + 121), a sub base material became exposed (122). This consisted of sand and gravel with core rubble of stone and brick, all late 20<sup>th</sup> century in date. This deposit averaged approximately 0.15m in depth. Below this deposit was natural grey clay and shale bedrock (123). At the point between the side wall of the house and the edge of the modern concrete steps several fragments of 18<sup>th</sup> century North Devon or glazed Dyfed Gravel Tempered Ware were recovered (these were not retained). No pottery fragments or any other dateable material was recovered earlier than the 18<sup>th</sup> century in this area. This would suggest that this area had already been disturbed previously, given that this end of the house appears to be early 17<sup>th</sup> century in date.

- 4.38 Once the natural bedrock was exposed ground reduction work continued to the



necessary depth, cutting into the bedrock, to lay the series of required drainage pipes.

ii) *ST2 - Service trench alongside proposed Kitchen extension – ST2 (see Figure 15)*

- 4.39 This fairly long trench, approximately 8m in length x 0.50m wide, was positioned along the line of an existing water issue, which diverted water from the upward slope away from the house. Looking at the early OS map of 1889, this issue is marked and it is very likely that this small water course had been taking water away from the house for several centuries. Development proposals intended to widen this course to insert an appropriate drainage pipe, presently absent, to a maximum depth of 1.30m in the deepest area below the present surface in order to allow a steep angle for drainage.
- 4.40 Groundwork initially removed the turf and top soil (113) along the existing water course route. This deposit averaged approximately 0.20m in depth. Dateable finds from this context were all 20<sup>th</sup> century and late 19<sup>th</sup> century in date and included glass bottle shards and pottery fragments (not retained). Removal of the top soil exposed a dark earth sub deposit (124), which appeared to have been previously disturbed, given that it included a mixture of 19<sup>th</sup> and 20<sup>th</sup> century midden material. The depth of this deposit varied, from between 0.40m -1.00m. Below this context, groundwork exposed a natural grey clay and shale bedrock (119/123).
- 4.41 However, toward the northern end of this trench, lying immediately above the natural bedrock and below the deposit of 19<sup>th</sup>/20<sup>th</sup> century midden material, was the remains of a low dry stone garden wall (125) that appeared in the side of the trench in the east facing section. This low wall, approximately 0.75m high x 0.40m wide, bordered the covered remains of a garden path consisting of square quarry tiles (138), identical to those that had existed within the earlier kitchen extension interior. This path appears to have once led toward the former 19<sup>th</sup> century kitchen extension entrance, the wall also having acted as a retaining wall for a lawn or flower bed area to the north. Directly lying on top this footpath was a deposit of late 19<sup>th</sup> and 20<sup>th</sup> century rubbish material, which further suggested that this area had been extensively landscaped in recent years.

iii) *ST3 - Service trench at front of house (see Figure 16)*

- 4.42 The service trench in front of the house entailed groundwork for the insertion of a foul drain with an inspection cover and linking up with existing drains.
- 4.43 Initial work in this area entailed the cutting back and removal of the existing front entrance steps in order to expose the existing foul drain. This work revealed that the foul pipe from the upstairs toilet has been cleverly hidden within the hollow decorative pilaster on the east side of the front entrance. This drain pipe was plastic, which suggested that this work had been done at some time in the late 20<sup>th</sup> century. Further removal of the side steps arrangement on the west side of the front entrance revealed that these side steps were also a later addition, which had been constructed from modern concrete blocks with a rubble core, which suggests that the original late 17<sup>th</sup> century step arrangement had most likely been central to the house entrance, as they were now to be constructed as per the development proposal.
- 4.44 Removal of this modern step arrangement also revealed that the front of the house had received several different colours of paint over the years, the earliest being a rose or pale red, followed by a dark cream or biscuit coloured paint.



- 4.45 Once the greater part of the step arrangement had been removed and the foul pipe was adequately exposed, the groundwork for the service trench began.
- 4.46 Once the turf and top soil (127) was removed, which reached a depth of only 0.15m, a beige/pale orange clay, intermixed with grit, charcoal fragments and lumps of processed lime (128) became exposed. This deposit averaged approximately 0.10m in depth. The character of this deposit suggested that it was a construction layer. All dateable finds recovered from this deposit were 19<sup>th</sup> and 20<sup>th</sup> century in date.
- 4.47 Directly below this deposit was a compacted pale green/grey clay intermixed with crushed grey shale (129), suggestive of a former path or track, likely an earlier footpath that led to the former entrance of the house in the 19<sup>th</sup> and 18<sup>th</sup> centuries. This compacted layer averaged approximately 0.10m in depth. From observation of an exposed section following the removal of part of the walling at the front of the house, this deposit also appeared to be bowed in its central area, again suggestive of a former footpath.
- 4.48 Below this deposit was a layer of crushed dark slate/shale intermixed with grey clay and ash and charcoal fragments with lime mortar (130). This deposit averaged approximately 0.20m in depth. This deposit was interpreted as a construction deposit and very likely late 17<sup>th</sup> century in date laid down during the construction of the late 17<sup>th</sup> century house. No dateable finds were recovered from this deposit.
- 4.49 Below this deposit was a natural beige/pale orange clay (131).
- iv) *ST4 - Service trench from front of house running southwards toward the main sewer (see Figure 17)*
- 4.50 This service trench extended from the front of the house, alongside the front garden enclosure wall, then southward toward the entrance to the farmstead enclosure, with the intention being to link up with the main sewer in the field to the south. The average depth of this trench was to be approximately 0.75m deep x 0.75m wide.
- 4.51 Across the entire length of this trench, the only significant feature that became exposed was the position of an east to west culvert (132), with the exposed section positioned alongside the entrance to the red brick built barn. The angle of this exposed section of culvert inferred that the culvert continued onwards toward the pond in the southwest part of the walled enclosure.
- 4.52 With regard the stratigraphy in this trench, a typical section comprised approximately 0.20m of compacted earth and shale (133). This deposit averaged approximately 0.20m in depth. Finds recovered from this deposit included occasional 19<sup>th</sup> century pottery fragments (not retained). Below this context was a deposit of loose earth and shale (134) with the occasional lens of ash intermixed with earth. This deposit averaged approximately 0.20m in depth. Below this deposit was a natural pale grey and iron stained shale grit (135).
- v) *ST5 - Service trenches in courtyard area*
- 4.53 The stratigraphy for this network of proposed service trenches was identical to that observed in Service Trench 4. No finds earlier than the 19<sup>th</sup> century were recovered, suggesting that the courtyard area had been landscape or cleared in either the 19<sup>th</sup> century.



### *Standing Building Investigation*

- 4.54 Following the removal of plasterwork from parts of the interior of the house, two significant features became exposed.
- 4.55 The first of these features was an apparent blocked in window on the first floor landing, within the west wall in the old part of the house (see Photo Plate 30). This former window opening would once have been part of the early 17<sup>th</sup> century house prior to the construction of the new extension house in the late 17<sup>th</sup> century. This is evident by the existence of the same fabric and mortar used as blocking in as the stone used in the main fabric of the later build.
- 4.56 The second significant feature exposed following the removal of plasterwork from the interior of the house is evidence for a blocked in 'bread oven' in the Lower Parlour Room, already mentioned in section 4.15. This feature appears to have been associated with the stone built roof tiled structure at the rear of the house in the north wall. Its character and form suggests that it was an extension bread oven. However, with the discovery of a slaked lime processing pit in the Lower Parlour Room, which appears to have had an association with this blocked in feature, that being to dispel lime processing fumes from the room, it is also possible that this structure also served another unknown function.
- 4.57 Regarding the exterior of the building, the investigation of the standing fabric, following the removal of external render and examination of existing exposed fabric at the rear of the house, exposed only a few interesting features associated with the early 17<sup>th</sup> century house and its incorporation into the late 17<sup>th</sup> century construction and changing architectural fashions.
- 4.58 Unsurprisingly, the majority of these features exist in areas where the two phases of building exist, particularly in the west wall of the early 17<sup>th</sup> century house and the join between the early and later 17<sup>th</sup> century house. Features here include; a blocked in window at first floor level adjacent to the joint between the west wall of the early 17<sup>th</sup> century house and the north wall of the late 17<sup>th</sup> century house; evidence for a former slit window at ground floor level in the west wall of the early 17<sup>th</sup> century house, south of the main entrance in this wall; evidence in the standing fabric that all of the window openings in the west wall of the early 17<sup>th</sup> century house have been altered to accommodate a change in window styles.
- 4.59 Other architectural features exposed in other parts of the house, include an unblocked window in the first floor of the east wall of the early 17<sup>th</sup> century house. This former window had been previously obscured by the kitchen roof and had been used at one time to allow light into the roof attic space, but had at one time more recently been panelled up.
- 4.60 Removal of the render from the external elevation of the front façade of the house revealed no new hidden features.

## **5 Conclusions and Recommendations**

- 5.1 The watching brief during the groundwork for the external services at Gilfach-y-berthog exposed only a few new interesting features that help shed some light on parts of the former 17<sup>th</sup> - 19<sup>th</sup> century farm complex.





- 5.2 The earliest of these features was the discovery of the partial remains of a cobbled floor in the area of the former stone barn at the north-western part of the complex. This cobbled surface is likely early 17<sup>th</sup> century in date, contemporary with the early 17<sup>th</sup> century house.
- 5.3 Other external features included a the partially exposed remains of a preserved low dry-stone built garden wall and a quarry tiled footpath that once led toward the back door of the 19<sup>th</sup> century kitchen extension. Groundwork revealed that this footpath and wall had been covered over and the ground landscaped at some time in the 20<sup>th</sup> century.
- 5.4 Service groundwork at the front of the house revealed that the existing entrance step arrangement was 20<sup>th</sup> century in date, as was evident from the use of modern concrete blocks. Evidence for an earlier step arrangement however was evident within the core rubble of this later step, in the form of several rose/pale red painted block stones, which suggested that the original late 17<sup>th</sup>-19<sup>th</sup> century step arrangement was most probably only a very simple two or three step arrangement.
- 5.5 Also, it was discovered that both pilasters that flanked the front entrance were also 20<sup>th</sup> century in date, one of which had been cleverly put in place to conceal a foul pipe from the upstairs toilet.
- 5.6 Groundwork in this area also revealed that in the 17<sup>th</sup> and 18<sup>th</sup> centuries and perhaps the 19<sup>th</sup> century, the boundary wall in front the house had once been made up of compacted crushed grey shale, with evidence for a former footpath directly opposite the front door, which continued through the stone boundary wall.
- 5.7 The groundwork for the demolition of the existing 19<sup>th</sup> century kitchen and the cutting of new footings for the new extension exposed no archaeological features or deposits, revealing only that the 19<sup>th</sup> century kitchen extension appeared to have caused extensive landscaping of the immediate area and its walls had been built directly onto the natural shale bedrock.
- 5.8 Groundwork within the house was confined to the Lower Parlour Room. The proposed floor reduction work revealed that this room had once had a cobbled floor in the early 17<sup>th</sup> century, which was covering a network of stone capped drainage culverts, each having been cut into the natural shale bedrock. Investigation and planning of these culverts revealed that they had probably been constructed in the early 17<sup>th</sup> century to direct water away from the rear of the house at its northern side.
- 5.9 Investigation and recording of the cobbled surface in the Lower Parlour Room revealed the remains of what has been interpreted as a slaked lime processing pit, which appeared to be 18<sup>th</sup> century in date, given that it post dated the cobbled floor and the red bricks used in its construction appeared to be early 18<sup>th</sup> century in character type. Examination of the walls in the Lower Parlour revealed that the slaked lime remains in the lime pit were identical to the slaked lime existing at the base of the lower parlour room walls, which would suggest that the slaked lime pit was used to produce slaked lime for use on the interior walls of the house in the 18<sup>th</sup> century.
- 5.10 One further feature exposed in the Lower Parlour Room was an apparent block-in in the fabric of the northern wall, on the eastern side of the inglenook fireplace. This opening was unblocked temporarily, which revealed that the opening led directly to a small external stone built structure at the rear of the house, which has been interpreted



as an extension bread oven, which appears to have also been used to help direct lime processing fumes out of the room during times of slaked lime production. The reason why this lime processing was undertaken inside the house was probably for several reasons, firstly, to keep the slaked lime close to the location of its proposed use and secondly, to avoid the lime processing getting too wet from the welsh rain.

- 5.11 With regards to the investigation of the standing fabric following internal and external render removal, there were only a small number of architectural features that became exposed that helped inform the chronology and development of the house. These features were predominantly in the west facing elevation of the early 17<sup>th</sup> century house. Features included a blocked in window, a former window slit and the apparent reduction in window sizes in the first and second floor windows.
- 5.12 In conclusion, the watching brief and the investigation of the standing fabric at Gilfach-y-berthog revealed that the earliest part of the existing house is early 17<sup>th</sup> century in date. This earlier house is at the northern end of the main house and occupies the lower level and basement area. This earlier house appears to have been extended in the late 17<sup>th</sup> century with the addition of an east to west aligned front facade, built in the 1690s, as is evident from the date of 1692 in the front parlour room. This construction work retained the original south facing external wall of the earlier house, which now forms part of the upper parlour room.
- 5.13 As there is apparently mention of a house at Gilfach in 12<sup>th</sup> century manuscripts, the footings of this medieval house were either completely removed in the early 17<sup>th</sup> century during construction of the first 17<sup>th</sup> century house, or else, medieval foundations are positioned in another area of the walled farmstead complex. However, given that the existing house is built directly onto the natural shale bedrock, it is very possible that the medieval footings were completely removed during preparation work for construction and stone re-used. Again, however, if this were the case, then you would still expect to have found some archaeological evidence, such as pottery fragments, somewhere within the complex to confirm this medieval identity. There were no pottery fragments recovered from any of the ground work earlier than the early 17<sup>th</sup> century.

## **6 Acknowledgements**

Thanks to; Davies Sutton Architects and Welsh Heritage Construction Ltd for allowing access to the house for recording and investigation works.

## **7 Bibliography and References**

Jones, F. 1987. *Historic Carmarthenshire Homes and their families*.

Dyfed Archaeological Report - DAT Ref: FS10-008-JM-170510

*OS Maps*

Ordnance Survey First Edition map of 1889 (1:2500)

Ordnance Survey Second Edition map of 1906 (1:2500)



## APPENDIX I:

### Figures

---








Figure 1.

Location map showing position of Gilfach-y-berthog, Carmarthenshire

Project Title: Gilfach-y-berthog, Carmarthenshire

Date: 30th July 2013

Scale: 1:50,000

Drawn by:

Drawing No.







Project Title: Giflach-y-berthog, Carmarthenshire

Date: 30th July 2013

Scale:

Drawn by:


Drawing No.

Figure 2.

Aerial Photo showing farmstead of Giflach-y-berthog

1. Introduction  
The purpose of this study is to investigate the effects of the proposed system on the performance of the system. The study is divided into two parts: a theoretical analysis and an experimental evaluation. The theoretical analysis is based on the principles of the system and the experimental evaluation is based on the results of the experiments.





Project Title: Gllfach-y-berthog, Carmarthenshire

Date: 30th July 2013


Scale:


Drawn by:

Drawing No.

**Figure 3.**

General Site Plan of Gllfach-y-berthog farmstead complex, with main house highlighted





Project Title: Glifach-y-berthog, Carmarthenshire

Date: 30th July 2013


Scale:

Drawn by:

Drawing No.

Figure 4.


Proposed general site plan (adapted from architect's plans)






0 20 meters

Project Title: Giliach-y-berthog, Carmarthenshire		Figure 5. Floor plans of existing main house (adapted from architects plans)		
Date: 30th July 2013	Scale:			
Drawn by:	Drawing No.			








Existing North Elevation



Existing East Elevation



Existing South Elevation



Existing West Elevation



Existing West Elevation

Project Title: Gllfach-y-berthog, Carmarthenshire

Date: 30th July 2013

Drawn by:


Scale:

Drawing No.

Figure 6.

Main House - Existing external elevations (adapted from architects plans)





Area of proposed ground  
reduction in Lower Parlour Room



Project Title: Giltfach-y-barthog, Carmarthenshire

Date: 30th July 2013

Scale:

Drawn by:

Drawing No.

Figure 7.


Ground plan of Lower Parlour Room and cellar/basement room, showing area of proposed ground reduction work within the interior of the house (adapted from original architects plans).





Legend

- Area of external trenches
- Route of proposed service trenches



0 50 meters

Project Title: Gllfach-y-berthog, Carmarthenshire

Date: 30th July 2013


Scale:

Drawn by: Drawing No.

Figure 8.

General site plan showing position of external groundworks and service trenches  
(adapted from original architects plans).






Project Title: Gllfach-y-bethog, Carmarthenshire		<b>Figure 9.</b> Ground plan showing area of proposed foundation trench for proposed new kitchen extension and position of service trenches ST1-ST4 (adapted from original architects plans).	Heritage Recording Services Wales
Date: 30th July 2013	Scale:		
Drawn by:	Drawing No.		









Project Title: Giffach-y-berthog, Carmarthenshire		<div><p>Heritage Recording Services Wales</p></div>
Date: 30th July 2013	Scale: Approx. 1:35 @A3	
Drawn by: RS Jones	Drawing No.	

**Figure 10.**


Main House - Lower Parlour Room - Ground Plan showing early 17th century cobbled floor (104), with 18th century repair at east end covering former 18th century slaked lime processing pit (106)





Project Title: Giliach-y-berthog, Carmarthenshire		Main House - Lower Parlour Room - Ground Plan showing early 17th century drainage culverts (109) and remains of 18th century slaked lime processing pit (106)	
Date: 30th July 2013	Scale: Approx. 1:35 @A3	Heritage Recording Services Wales	
Drawn by: RS Jones	Drawing No. 1		





Project Title: Gllfach-y-berthog, Carmarthenshire

Date: 30th July 2013

Drawn by: RS Jones


Scale: Approx. 1:100 @A3

Drawing No.


**Figure 12.**

Main House - Kitchen Extension - Ground Plan showing extent of demolition of existing kitchen extension and excavation extent for new Kitchen extension at east end of house.






Project Title: Gllfach-y-berthog, Carmarthenshire		<b>Figure 13.</b> Ground plan showing Service Trench No.1 (ST1) and Trench 1 (TR1) for new kitchen extension foundation	Heritage Recording Services Wales
Date: 30th July 2013	Scale: Approx. 1:100 @A3		
Drawn by: RS Jones	Drawing No.		









Project Title: Giffach-y-berthog, Carmarthenshire		<b>Figure 14.</b> Main House - West facing section drawing A-B in Trench 1 (kitchen extension)	
Date: 30th July 2013	Scale:		
Drawn by: RS Jones	Drawing No.		





Ground plan of Service trench 2 (ST2)



East facing section of service trench 2 (ST2)

Project Title: Gllfach-y-berthog, Camarthenshire

Date: 30th July 2013


Scale:


Drawn by: RS Jones

Drawing No.


Figure 15.


Gllfach-y-berthog - Ground plan and east facing section of Service Trench No.2 (ST2)





Project Title: Gllfach-y-berthog, Camarthenshire		Figure 16.	
Date: 30th July 2013	Scale:	Gllfach-y-berthog - Ground plan and south facing section of Service Trench No.3 (ST3)	
Drawn by: RS Jones	Drawing No.	Heritage Recording Services Wales	









Ground plan of service trench 4 (ST4)

Project Title: Gllfach-y-berthog, Carmarthenshire		<div> <div>Heritage</div> <div>Recording Services Wales</div> </div>
Date: 30th July 2013	Scale:	
Drawn by: RS Jones	Drawing No.	

Figure 17.  
Gllfach-y-berthog - Ground plan and typical east facing section of Service Trench No.4 (ST4)







Project Title: Giffach-y-berthog, Carmarthenshire

Date: 30th July 2013

Scale:


Drawn by: RS Jones

Drawing No.


**Figure 18.**

Giffach-y-berthog - Ground plan showing position of trenches 2-7 within former limber barn at southwestern end of farm complex, with trenches 2, 3 and 5 ground plans showing early 17th century cobbled surface.





Ordnance Survey First Edition map (1:2500) of 1889



Ordnance Survey Second Edition map (1:2500) of 1906

Project Title: Giffach-y-berthog, Carmarthenshire

Date: 30th July 2013

Scale:

Drawn by:

Drawing No.

Figure 19.

Giffach-y-berthog - Portions of Ordnance Survey First and Second Edition Maps of 1889 and 1906



## **APPENDIX II:**

### **Photo plates**





*Plate 1. View of Gilfach-y-berthog. Looking south.*



*Plate 2. Gilfach-y-berthog. Looking south-east.*

Project Title: Gilfach-y-berthog	Photo Plate No's. 1 and 2	
Date taken: February 2013		
Photographer: Richard Scott Jones		

1. The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that proper record-keeping is essential for the transparency and accountability of the organization. The text outlines the various methods used to collect and analyze data, ensuring that the information is reliable and up-to-date.

2. The second part of the document focuses on the implementation of the proposed changes. It details the steps involved in the process, from the initial planning stage to the final execution. The document highlights the challenges faced during the implementation and provides strategies to overcome them. It also mentions the role of the staff in ensuring the smooth transition to the new system.

3. The third part of the document discusses the future prospects of the organization. It outlines the long-term goals and the strategies to achieve them. The text mentions the need for continuous improvement and the importance of staying updated with the latest trends in the industry. It also mentions the role of the management in ensuring the organization's growth and success.

4. The fourth part of the document discusses the financial aspects of the organization. It provides a detailed analysis of the current financial status and the projected future performance. The text mentions the various sources of revenue and the expenses incurred. It also mentions the need for proper financial management and the importance of maintaining a healthy balance sheet.

5. The fifth part of the document discusses the human resources of the organization. It mentions the current staff strength and the need for recruitment to fill the vacant positions. The text also mentions the importance of providing training and development opportunities to the staff to enhance their skills and productivity. It also mentions the need for a fair and equitable compensation system.

6. The sixth part of the document discusses the legal aspects of the organization. It mentions the various laws and regulations that the organization is subject to. The text also mentions the need for proper legal counsel and the importance of ensuring compliance with the law. It also mentions the need for proper documentation of all transactions and the importance of maintaining the confidentiality of the organization's information.






*Plate 3. View of Gilfach-y-berthog. Looking west.*



*Plate 4. Gilfach-y-berthog. Front of house. Looking north.*

Project Title: Gilfach-y-berthog	Photo Plate No's. 3 and 4	
Date taken: February 2013		
Photographer: Richard Scott Jones		

Handwritten text, likely bleed-through from the reverse side of the page. The text is mostly illegible due to fading and bleed-through, but appears to be organized into several paragraphs. Some words like "the", "and", "of", "in", "to", "from", "at", "on", "with", "by", "for", "as", "is", "are", "was", "were", "be", "been", "have", "has", "had", "do", "does", "did", "shall", "should", "may", "might", "must", "can", "could", "will", "would", "do", "does", "did", "shall", "should", "may", "might", "must", "can", "could", "will", "would" are visible.








*Plate 5. View of Gilfach-y-berthog. Southwest facing elevation. Looking northeast.*



*Plate 6. Gilfach-y-berthog. Northeast facing elevation. Looking southwest.*

Project Title: Gilfach-y-berthog	Photo Plate No's. 5 and 6	
Date taken: February 2013		
Photographer: Richard Scott Jones		

1. The first part of the paper discusses the importance of the study of the history of the English language. It is argued that the study of the history of the English language is essential for a full understanding of the language and its development. The paper then goes on to discuss the various factors that have influenced the development of the English language, such as the influence of other languages, the influence of social and cultural changes, and the influence of technological advances.

2. The second part of the paper discusses the importance of the study of the history of the English language. It is argued that the study of the history of the English language is essential for a full understanding of the language and its development. The paper then goes on to discuss the various factors that have influenced the development of the English language, such as the influence of other languages, the influence of social and cultural changes, and the influence of technological advances.





Plate 7. Gylfach-y-berthog - Existing 19th century kitchen extension. Northeast facing elevation. Looking southwest.



Plate 8. Gylfach-y-berthog - View of rear entrance porch. Early 17th century house. Looking north.

Project Title: Gylfach-y-berthog

Date taken: February 2013

Photographer: Richard Scott Jones

Photo Plate No's. 7 and 8

**Heritage**  
Recording Services Wales







*Plate 9. Gilfach-y-berthog - View of rear entrance porch. Looking southeast.*



*Plate 10. Gilfach-y-berthog - Northeast facing elevation. Looking northwest.*

**Project Title:** Gilfach-y-berthog

**Date taken:** February 2013

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 9 and 10

**Heritage**  
Recording Services Wales







*Plate 11. Gilfach-y-berthog - Detail of front entrance porch in south facing elevation. Looking north.*



*Plate 12. Gilfach-y-berthog - Oven feature attached to rear northeast facing elevation. Looking west.*

**Project Title:** Gilfach-y-berthog

**Date taken:** May 2013

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 11 and 12

**Heritage**  
Recording Services Wales

1. The first part of the paper discusses the importance of the study of the history of the Chinese language and the role of the Chinese language in the development of the Chinese nation. It also discusses the relationship between the Chinese language and the Chinese culture.

2. The second part of the paper discusses the development of the Chinese language from ancient times to the present. It discusses the changes in the Chinese language over time and the influence of foreign languages on the Chinese language.

3. The third part of the paper discusses the current status of the Chinese language and the challenges it faces. It discusses the role of the Chinese language in the development of the Chinese nation and the world.

4. The fourth part of the paper discusses the future of the Chinese language and the role of the Chinese language in the development of the Chinese nation and the world.



*Plate 13. Gilfach-y-berthog - Interior view of ground floor Front Room (Parlour). Looking southwest.*



*Plate 14. Gilfach-y-berthog - Interior view of ground floor Front Room (Parlour). Looking west.*

**Project Title:** Gilfach-y-berthog

**Date taken:** 1st June 2013

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 13 and 14

**Heritage**  
Recording Services Wales








Plate 15. Gilfach-y-berthog - Northeast facing internal elevation of Front Room (Parlour). Looking southwest.



Plate 16. Gilfach-y-berthog - Stone fireplace in Front Room (Parlour). Looking south.

Project Title: Gilfach-y-berthog	Photo Plate No's. 15 and 16	
Date taken: May 2013		
Photographer: Richard Scott Jones		





*Plate 17. Gilfach-y-berthog - Front Room (Parlour). Detail on fireplace.*



*Plate 18. Gilfach-y-berthog - Front Room (Parlour). Southeast facing elevation. Looking northeast.*

**Project Title:** Gilfach-y-berthog

**Date taken:** May 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 17 and 18

**Heritage**  
Recording Services Wales

THE UNIVERSITY OF CHICAGO

PHYSICS DEPARTMENT

PHYSICS 341

PHYSICS 341





*Plate 19. Giffach-y-berthog - Front Room (Dining Room). Looking southwest.*



*Plate 20. Giffach-y-berthog - Front Room (Dining Room). Looking northeast.*

**Project Title:** Giffach-y-berthog

**Date taken:** May 2013

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 19 and 20

**Heritage**  
Recording Services Wales

1. The first part of the paper discusses the importance of the study of the history of the United States. It is argued that a knowledge of the past is essential for a full understanding of the present and for the development of a sound policy for the future.

2. The second part of the paper discusses the importance of the study of the history of the United States. It is argued that a knowledge of the past is essential for a full understanding of the present and for the development of a sound policy for the future.



Plate 21. Gilfach-y-berthog - Front Room (Dining Room). Detail of plasterwork and blank cartouch and date of 1692. Looking southeast.



Plate 22. Gilfach-y-berthog - Lower Parlour rRoom prior to groundwork. Looking north.

Project Title: Gilfach-y-berthog

Date taken: May 2013

Photographer: Richard Scott Jones

Photo Plate No's. 21 and 22

**Heritage**  
Recording Services Wales

Handwritten text in the top section, possibly a header or title area.


Main body of handwritten text, consisting of several lines of cursive script.



Plate 23. Giffach-y-berthog - Basement Room. Looking west.



Plate 24. Giffach-y-berthog - Basement Room. Looking east.

Project Title: Giffach-y-berthog	Photo Plate No's. 23 and 24	
Date taken: May 2013		
Photographer: Richard Scott Jones		

1. The first part of the paper discusses the importance of the study of the history of the United States.

2. The second part of the paper discusses the importance of the study of the history of the United States.

3. The third part of the paper discusses the importance of the study of the history of the United States.

4. The fourth part of the paper discusses the importance of the study of the history of the United States.





*Plate 25. Gilfach-y-berthog - Existing kitchen extension at east end of house. Looking north.*



*Plate 26. Gilfach-y-berthog - Existing kitchen extension at east end of house. Looking southeast.*

**Project Title:** Gilfach-y-berthog

**Date taken:** May 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 25 and 26

**Heritage**  
Recording Services Wales







*Plate 27. Giffach-y-berthog - Existing kitchen extension at east end of house. Looking south.*



*Plate 28. Giffach-y-berthog - Downstairs toilet at east end of house. Looking east.*

**Project Title:** Giffach-y-berthog

**Date taken:** May 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 27 and 28

**Heritage**  
Recording Services Wales





*Plate 29. Gilfach-y-berthog - Downstair hall. Looking west.*



*Plate 30. Gilfach-y-berthog - Evidence for blocked in 1st floor window in west wall of former early 17th century house. Looking west.*

**Project Title:** Gilfach-y-berthog

**Date taken:** May 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 29 and 30

**Heritage**  
Recording Services Wales





*Plate 31. Gilfach-y-berthog - First floor bedroom..Looking west.*



*Plate 32. Gilfach-y-berthog - First floor bedroom. Looking north.*

**Project Title:** Gilfach-y-berthog

**Date taken:** May 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 31 and 32

**Heritage**  
Recording Services Wales

1. The first part of the document discusses the importance of maintaining accurate records of all transactions and the role of the accounting department in ensuring the integrity of the financial statements. It also highlights the need for regular audits and the importance of transparency in financial reporting.

2. The second part of the document focuses on the implementation of internal controls to prevent fraud and ensure the accuracy of financial data. It outlines the key components of a robust internal control system, including segregation of duties, authorization procedures, and regular monitoring and evaluation.

3. The third part of the document addresses the challenges faced by organizations in managing their financial resources effectively. It discusses the importance of budgeting and forecasting, and the role of the accounting department in providing accurate and timely financial information to support decision-making.

4. The fourth part of the document explores the impact of technology on the accounting profession. It discusses the benefits of automation and the use of data analytics in financial reporting, and the need for accountants to stay updated on the latest technological advancements.

5. The fifth part of the document concludes by emphasizing the importance of ethical behavior in the accounting profession. It discusses the role of accountants as trusted advisors and the need to adhere to the highest standards of professional conduct.





Plate 33. Gilfach-y-berthog - First floor landing. Looking east.



Plate 34. Gilfach-y-berthog - Second floor bedroom. Looking northwest.

Project Title: Gilfach-y-berthog

Date taken: May 2012

Photographer: Richard Scott Jones

Photo Plate No's. 33 and 34

Heritage  
Recording Services Wales

11

24

1

2

3






*Plate 35. Gilfach-y-berthog - Second floor landing. Looking north.*



*Plate 36. Gilfach-y-berthog - Second floor bedroom. Looking southwest.*

<b>Project Title:</b> Gilfach-y-berthog	<b>Photo Plate No's.</b> 35 and 36	
<b>Date taken:</b> May 2012		
<b>Photographer:</b> Richard Scott Jones		

1. The first part of the paper discusses the importance of the study of the history of the United States. It is argued that a knowledge of the past is essential for a full understanding of the present and for the development of a sound policy for the future.

2. The second part of the paper discusses the role of the government in the development of the United States. It is argued that the government has played a crucial role in the development of the country, and that its actions have been guided by a set of principles that have been passed down from generation to generation.

3. The third part of the paper discusses the role of the individual in the development of the United States. It is argued that the individual has played a crucial role in the development of the country, and that his actions have been guided by a set of principles that have been passed down from generation to generation.

4. The fourth part of the paper discusses the role of the future in the development of the United States. It is argued that the future is a time of great opportunity, and that it is up to us to make the most of it.



*Plate 37. Gylfach-y-berthog - First floor Bedroom 2. Front of house. Looking east.*



*Plate 38. Gylfach-y-berthog - First floor Bedroom 2. Front of house. Detail of plasterwork fireplace. Looking northeast.*

**Project Title:** Gylfach-y-berthog

**Date taken:** May 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 37 and 38

**Heritage**  
Recording Services Wales





*Plate 39. Gilfach-y-berthog - Landing area to attic room. Looking north.*



*Plate 40. Gilfach-y-berthog - 'A' frame in 1st floor attic room. Northern range. Looking northwest.*

**Project Title:** Gilfach-y-berthog

**Date taken:** May 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 39 and 40

**Heritage**  
Recording Services Wales







*Plate 41. Gilfach-y-berthog - 'A' frame in 2nd floor attic room. Southern range. Looking east.*



*Plate 42. Gilfach-y-berthog - Detail of 'A' frame in 2nd floor attic room. Looking west.*

**Project Title:** Gilfach-y-berthog

**Date taken:** May 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 41 and 42

**Heritage**  
Recording Services Wales







Plate 43. Working shot during removal of modern concrete steps for drainage services (ST1). Looking northeast.




Plate 44. Working shot following removal of modern concrete base at rear of house (ST1). Looking east.

**Project Title:** Giffach-y-berthog

**Date taken:** February 2012

**Photographer:** Richard Scott Jones

**Photo Plates No's.** 43 and 44







*Plate 45. Galfach-y-berthog - Northwestern corner of rear of house following removal of modern steps and concrete (ST1). Looking east.*



*Plate 46. Galfach-y-berthog - Rear of house following removal of modern concrete base and ground reduction for drainage (ST1). Looking west.*

**Project Title:** Galfach-y-berthog

**Date taken:** February 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 45 and 46

**Heritage**  
Recording Services Wales





*Plate 47. Gilfach-y-berthog - Floor surface in Lower Parlour Room prior to floor reduction. Looking northeast.*



*Plate 48. Gilfach-y-berthog - Floor surface in Lower Parlour Room prior to floor reduction. Looking west.*

**Project Title:** Gilfach-y-berthog

**Date taken:** February 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 47 and 48

**Heritage**  
Recording Services Wales



Handwritten text, possibly a signature or a date, located in the upper-right quadrant of the page. The text is very faint and difficult to read.





*Plate 49. Gilfach-y-berthog - Working shot during removal of modern stone floor tiles from Lower Parlour Room during ground reduction. Looking southwest.*



*Plate 50. Gilfach-y-berthog - Floor surface in Lower Parlour Room following removal of modern stone floor tiles. Looking northwest.*

**Project Title:** Gilfach-y-berthog

**Date taken:** February 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 49 and 50

**Heritage**  
Recording Services Wales








Plate 51. Gilfach-y-berthog - Floor surface in Lower Parlour Room following removal of modern stone floor tiles. Looking southeast.



Plate 52. Gilfach-y-berthog - Floor surface in Lower Parlour Room following removal of modern stone floor tiles and underlying earth and mortar deposit, showing partial remains of former cobbled floor. Looking southwest.

Project Title: Gilfach-y-berthog

Date taken: February 2012

Photographer: Richard Scott Jones

Photo Plate No's. 51 and 52

Heritage  
Recording Services Wales





*Plate 53. Gilfach-y-berthog - Remains of former early 17th century cobbled floor in Lower Parlour Room following ground reduction work. Looking west.*



*Plate 54. Gilfach-y-berthog - Remains of former early 17th century cobbled floor in Lower Parlour Room following ground reduction work. Looking southeast.*

**Project Title:** Gilfach-y-berthog

**Date taken:** February 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 53 and 54

**Heritage**  
Recording Services Wales

1. The first part of the paper discusses the importance of the study of the history of the United States. It is argued that a knowledge of the past is essential for a full understanding of the present and for the development of a sound policy for the future.

2. The second part of the paper discusses the role of the individual in the history of the United States. It is argued that the actions of individuals have played a major role in the development of the country and that it is important to study the lives of the great men and women of the past.

3. The third part of the paper discusses the role of the government in the history of the United States. It is argued that the government has played a major role in the development of the country and that it is important to study the actions of the government in the past.

4. The fourth part of the paper discusses the role of the people in the history of the United States. It is argued that the actions of the people have played a major role in the development of the country and that it is important to study the actions of the people in the past.

5. The fifth part of the paper discusses the role of the future in the history of the United States. It is argued that the actions of the future will play a major role in the development of the country and that it is important to study the actions of the future in the past.





Plate 55. Remains of early 17th century cobbled floor beneath modern stone floor tiles in Lower Parlour Room. Looking northwest.

**Project Title:** Gllfach-y-berthog

**Date taken:** June 2013

**Photographer:** Richard Scott Jones

**Photo Plates No.** 55

Handwritten text, likely bleed-through from the reverse side of the page. The text is extremely faint and illegible due to the quality of the scan. It appears to be a list or a series of entries, possibly names and dates, but cannot be transcribed accurately.





Plate 56. Remains of early 17th century cobbled floor beneath modern stone floor tiles in Lower Parlour Room. Looking north.

**Project Title:** Gylfach-y-berthog

**Date taken:** June 2013

**Photographer:** Richard Scott Jones

**Photo Plates No.** 56







Plate 57. Remains of early 17th century cobbled floor beneath modern stone floor tiles in Lower Parlour Room. Looking northwest.

**Project Title:** Giffach-y-berthog

**Date taken:** June 2013

**Photo Plates No.** 57

**Photographer:** Richard Scott Jones







Plate 58. Remains of early 17th century cobbled floor beneath modern stone floor tiles in Lower Parlour Room. Slaked Lime pit in foreground covered by cobble repair. Looking northeast

**Project Title:** Giffach-y-berthog

**Date taken:** June 2013

**Photographer:** Richard Scott Jones

**Photo Plates No.** 58








Plate 59. View of area of repaired cobbled floor covering slaked lime pit. Looking south.



Plate 60. View of area of repaired cobbled floor covering slaked lime pit. Looking north.

**Project Title:** Gllfach-y-barthog

**Date taken:** June 2013

**Photo Plates No.** 59 and 60

**Photographer:** Richard Scott Jones







Plate 61. Gylfach-y-berthog - Southern edge of repaired area of cobbled floor covering lime pit. Looking north.



Plate 62. Gylfach-y-berthog - Exposed slaked lime pit following removal of cobbled floor. Looking north.

Project Title: Gylfach-y-berthog	Photo Plate No's. 61 and 62	
Date taken: June 2013		
Photographer: Richard Scott Jones		







Plate 70. Gilfach-y-berthog - Exposed slaked lime pit following removal of cobbled floor and exposing of culvert channels. Looking northeast.



Plate 71. Gilfach-y-berthog - Fireplace opening with exposed cobbled floor at base. Looking northwest.

Project Title: Gilfach-y-berthog	Photo Plate No's. 70 and 71	
Date taken: June 2013		
Photographer: Richard Scott Jones		

1. The first part of the paper discusses the importance of the study of the history of the United States. It is argued that a knowledge of the past is essential for a full understanding of the present and for the development of a sound policy for the future. The author points out that the study of history is not only a means of acquiring knowledge, but also a means of developing the ability to think critically and to make sound judgments.

2. The second part of the paper discusses the importance of the study of the history of the United States. It is argued that a knowledge of the past is essential for a full understanding of the present and for the development of a sound policy for the future. The author points out that the study of history is not only a means of acquiring knowledge, but also a means of developing the ability to think critically and to make sound judgments.

3. The third part of the paper discusses the importance of the study of the history of the United States. It is argued that a knowledge of the past is essential for a full understanding of the present and for the development of a sound policy for the future. The author points out that the study of history is not only a means of acquiring knowledge, but also a means of developing the ability to think critically and to make sound judgments.





*Plate 72. Gylfach-y-berthog - Cobbled surface in area of fireplace and bread oven in fireplace side wall. Looking east.*



*Plate 73. Gylfach-y-berthog - Remains of cobbled surface in fireplace opening. Looking northwest.*

**Project Title:** Gylfach-y-berthog

**Date taken:** June 2013

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 72 and 73

**Heritage**  
Recording Services Wales








*Plate 74. Gylfach-y-berthog - TR2 - Exposed cobbled floor in area of stone barn during concrete pier support trenches.*



*Plate 75. Gylfach-y-berthog - TR3 - Exposed cobbled floor in area of stone barn during concrete pier support trenches.*

Project Title: Gylfach-y-berthog	Photo Plate No's. 74 and 75	
Date taken: June 2013		
Photographer: Richard Scott Jones		

1. The first part of the paper discusses the importance of the study of the history of the United States. It is argued that a knowledge of the past is essential for a full understanding of the present. The author points out that the United States has a long and rich history, and that it is important to study the events and people that have shaped the nation. The author also discusses the role of the government in the development of the country, and the importance of the Constitution. The paper concludes by stating that the study of the history of the United States is a vital part of the education of every citizen.

2. The second part of the paper discusses the role of the government in the development of the United States. It is argued that the government has played a central role in the growth of the nation, and that it is responsible for the success of the country. The author points out that the government has been instrumental in the development of the infrastructure, the education system, and the economy. The author also discusses the role of the government in the protection of the rights of citizens, and the importance of the rule of law. The paper concludes by stating that the government is a vital part of the United States, and that it is essential for the country to have a strong and effective government.

3. The third part of the paper discusses the role of the people in the development of the United States. It is argued that the people are the foundation of the nation, and that they are responsible for the success of the country. The author points out that the people have played a central role in the development of the United States, and that they are the ones who have shaped the nation. The author also discusses the role of the people in the protection of the rights of citizens, and the importance of the rule of law. The paper concludes by stating that the people are the most important part of the United States, and that it is essential for the country to have a strong and active citizenry.





Plate 76. Gilfach-y-berthog - Working shot during groundwork for proposed kitchen extension. Looking northeast.



Plate 77. Gilfach-y-berthog - Stratigraphy in area of proposed kitchen extension following groundwork. Looking east.

Project Title: Gilfach-y-berthog


Date taken: April 2013

Photographer: Richard Scott Jones

Photo Plate No's. 76 and 77

**Heritage**  
Recording Services Wales







*Plate 78. Gilfach-y-berthog - Working shot during groundwork for proposed kitchen extension. Looking north.*



*Plate 79. Gilfach-y-berthog - Former 19th century kitchen extension demolished in preparation for new proposed kitchen extension.*


**Project Title:** Gilfach-y-berthog

**Date taken:** April 2013

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 78 and 79

**Heritage**  
Recording Services Wales







*Plate 80. Gilfach-y-berthog - Former 19th century kitchen extension demolished in preparation for new proposed kitchen extension. East facing elevation.*



*Plate 81. Gilfach-y-berthog - Former 19th century kitchen extension demolished in preparation for new proposed kitchen extension. East facing elevation.*

**Project Title:** Gilfach-y-berthog

**Date taken:** April 2013

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 80 and 81

**Heritage**  
Recording Services Wales






*Plate 82. Gylfach-y-berthog - Former 19th century kitchen extension demolished in preparation for new proposed kitchen extension. Note earlier extension outline. North facing elevation.*



*Plate 83. Gylfach-y-berthog - Former 19th century kitchen extension demolished in preparation for new proposed kitchen extension. Detail at base of north facing rear wall of late 17th century house. Looking southeast.*

<b>Project Title:</b> Gylfach-y-berthog	<b>Photo Plate No's.</b> 82 and 83	
<b>Date taken:</b> April 2013		
<b>Photographer:</b> Richard Scott Jones		







*Plate 84. Gylfach-y-berthog - Service trench (ST2) alongside new kitchen extension. Looking south.*



*Plate 85. Gylfach-y-berthog - Service trench (ST2) alongside new kitchen extension. Looking south.*

**Project Title:** Gylfach-y-berthog

**Date taken:** September 2013

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 84 and 85

**Heritage**  
Recording Services Wales

1. The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that proper record-keeping is essential for the transparency and accountability of the organization. The text outlines the various methods used to collect and analyze data, ensuring that the information is reliable and up-to-date.

2. The second part of the document focuses on the implementation of the proposed changes. It details the steps involved in the process, from the initial planning stage to the final execution. The document highlights the challenges faced during the implementation and provides solutions to overcome them. It also discusses the role of the management team in ensuring the successful completion of the project.

3. The third part of the document provides a summary of the findings and conclusions. It summarizes the key points discussed in the previous sections and provides a clear overview of the results. The document concludes by emphasizing the importance of continuous monitoring and evaluation to ensure the long-term success of the project.

4. The fourth part of the document discusses the future directions of the project. It outlines the goals and objectives for the next phase of the project and provides a timeline for the completion of the work. The document also discusses the potential risks and challenges that may arise and provides strategies to mitigate them. It concludes by expressing confidence in the ability of the team to achieve the desired outcomes.

5. The fifth part of the document provides a list of references and sources used in the document. It includes a list of books, articles, and other documents that have been consulted during the research process. The list is organized alphabetically by author's name.

6. The sixth part of the document provides a list of appendices and supplementary materials. It includes a list of tables, figures, and other documents that are included in the document. The list is organized by the order in which they appear in the document.

7. The seventh part of the document provides a list of acknowledgments. It expresses gratitude to the individuals and organizations that have provided support and assistance during the project. The list includes the names of the individuals and organizations and a brief description of their contributions.

8. The eighth part of the document provides a list of contact information. It includes the names and titles of the individuals responsible for the project and provides their contact details. The list is organized by the order in which they appear in the document.

9. The ninth part of the document provides a list of other relevant information. It includes a list of other documents and materials that are related to the project. The list is organized by the order in which they appear in the document.

10. The tenth part of the document provides a list of other relevant information. It includes a list of other documents and materials that are related to the project. The list is organized by the order in which they appear in the document.






*Plate 86. Gylfach-y-berthog - Service trench at front of house (ST4). Looking northwards.*



*Plate 87. Gylfach-y-berthog - Detail showing stratigraphy along length of service trench in front of house and red brick barn (ST4). Looking southwards.*

<b>Project Title:</b> Gylfach-y-berthog	<b>Photo Plate No's.</b> 86 and 87	
<b>Date taken:</b> September 2013		
<b>Photographer:</b> Richard Scott Jones		



1000 1000 1000 1000





*Plate 88. Gilfach-y-berthog - Route of service trench in front of house (ST4). Looking northwards.*



*Plate 89. Gilfach-y-berthog - Service trench (ST4) following groundwork. Looking northwards.*

**Project Title:** Gilfach-y-berthog

**Date taken:** September 2013

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 88 and 89

**Heritage**  
Recording Services Wales








*Plate 90. Gilfach-y-berthog - Stratigraphy in service trench (ST4). East facing section. Looking northwards.*



*Plate 91. Gilfach-y-berthog - Stratigraphy in service trench (ST4). East facing section. Looking southwards.*

Project Title: Gilfach-y-berthog	Photo Plate No's. 90 and 91	
Date taken: September 2012		
Photographer: Richard Scott Jones		

THE  
FEDERAL  
BUREAU OF  
INVESTIGATION  
OF THE  
DEPARTMENT OF JUSTICE  
WASHINGTON, D. C. 20535

REPORT OF THE  
FEDERAL BUREAU OF  
INVESTIGATION  
ON THE  
ACTS AND OMISSIONS  
OF THE  
UNITED STATES  
DEPARTMENT OF JUSTICE  
IN THE  
CASE OF  
THE  
FEDERAL BUREAU OF  
INVESTIGATION  
OF THE  
DEPARTMENT OF JUSTICE  
WASHINGTON, D. C. 20535

REPORT OF THE  
FEDERAL BUREAU OF  
INVESTIGATION  
ON THE  
ACTS AND OMISSIONS  
OF THE  
UNITED STATES  
DEPARTMENT OF JUSTICE  
IN THE  
CASE OF  
THE  
FEDERAL BUREAU OF  
INVESTIGATION  
OF THE  
DEPARTMENT OF JUSTICE  
WASHINGTON, D. C. 20535





Plate 92. Gilfach-y-berthog - Stratigraphy in front of house alongside former entrance steps (ST3). Looking northwards.



Plate 93. Gilfach-y-berthog - Working shot during groundwork for services (ST3) in front of house. Looking west.

Project Title: Gilfach-y-berthog

Date taken: February 2012

Photographer: Richard Scott Jones

Photo Plate No's. 92 and 93

Heritage  
Recording Services Wales







*Plate 94. Galfach-y-berthog - Demolition of former steps at front of house. Looking eastwards.*



*Plate 95. Galfach-y-berthog - Exposed stratigraphy in raised area alongside front of house. Looking eastwards.*

**Project Title:** Galfach-y-berthog


**Date taken:** September 2012

**Photographer:** Richard Scott Jones

**Photo Plate No's.** 94 and 95


**Heritage**  
Recording Services Wales





## **APPENDIX III:**

### **Contexts Register**



# Gilfach-y-Berthog

## CONTEXTS REGISTER

*All contexts start at 100*

### **CONTEXTS**

#### **A) Internal Ground Work**

##### *Ground Floor Lower Parlour Room*

100 = Modern flagstone floor

101 = Modern flagstone bedding deposit, consisting of sand and pea-grit. Approximately 0.02m in depth

102 = Modern polyurethane plastic membrane

103 = Stone and earth levelling and core deposit for modern flagstone floor (100). Approximately 0.10m in depth.

104 = Early 17<sup>th</sup> century cobbled floor. River cobbles vary in size from 0.05 – 0.20m. Cobbled floor covers approximately 70% of the parlour room floor, with areas alongside both doorways at the west end being absent of any stones, suggesting that these areas once held large slate slabs since robbed or removed prior to covering of floor in the later centuries. Evidence of cobbled floor repair at east end with replacement black slate and red brick.

105 = Position of former early 17<sup>th</sup> century stone slab that must have once invited access to a former doorway in the southern partition wall of the early 17<sup>th</sup> century house, now blocked.

106 = Remains of former 19<sup>th</sup> century slaked lime processing pit

107 = Remains of slaked lime on floor covering cobbles, having dripped down from walls.

108 = Cut through cobbled floor (104) for insertion of 20<sup>th</sup> century electric cable trench. Filled by (103).

109 = Cobbled floor bedding deposit, consisting of dark earth and small stones. Averaged approximately 0.05 – 0.10m in depth.

110 = Early 17<sup>th</sup> century drainage culverts. Consists of large capping stones covering narrow drainage channels cut into natural bedrock. Drainage water flowed from north to south. Helped direct rain water away from house.

111 = Natural grey coloured shale/slate bedrock

112 = Position of 19<sup>th</sup> century former chimney flue in north wall, associated with former slack lime processing pit. Helped to extract smoke and fumes during slaked lime processing.

1949

1. The first part of the report deals with the general situation in China, and the second part deals with the specific situation in the various provinces.

2. The first part of the report deals with the general situation in China, and the second part deals with the specific situation in the various provinces.

3. The first part of the report deals with the general situation in China, and the second part deals with the specific situation in the various provinces.

4. The first part of the report deals with the general situation in China, and the second part deals with the specific situation in the various provinces.

5. The first part of the report deals with the general situation in China, and the second part deals with the specific situation in the various provinces.

6. The first part of the report deals with the general situation in China, and the second part deals with the specific situation in the various provinces.

## **B) External Ground Work**

### *Kitchen Extension*

113 = Top soil, averaging 0.20m in depth. Finds recovered from this deposit included 20<sup>th</sup> century and late 19<sup>th</sup> century material (pottery, glass sherds etc).

114 = Natural grey shale/slate bedrock (same as context 111 exposed in Lower Parlour Room in house).

### *Pier Supports in Barn for new Garage*

115 = Modern concrete floor

116 = Sub base beneath modern concrete floor, consisting of earth, stones and sand.

117 = Dark earth deposit, intermixed with soot and ash.

118 = Cobbled floor. Likely early 17<sup>th</sup> century in date.

119 = Natural shale bedrock.

### *Service trenches*

120 = Modern concrete support base at rear of house. Originally constructed to support heating oil tank and boiler house.

121 = Modern concrete paving slab steps at side of house at rear.

122 = Sub base below contexts 120 and 121.

123 = Natural shale bedrock (same as 111 and 114).

124 = Dark earth deposit intermixed with 19<sup>th</sup> and 20<sup>th</sup> century midden material.

125 = Low dry-stone garden wall. Likely 19<sup>th</sup> century in date.

126 = Garden path constructed from 6 inch square quarry tiles (19<sup>th</sup> century in date).

127 = Turf and top soil in service trench 3.

128 = Deposit of beige/pale orange clay intermixed with grit, ash, charcoal fragments and lumps of processed lime in service trench 3.

129 = Deposit of pale green/grey clay intermixed with crushed grey shale. Likely former 19<sup>th</sup> and 18<sup>th</sup> century footpath in service trench 3.

130 = Deposit of crushed dark slate/shale intermixed with grey clay and ash and charcoal fragments with lime mortar. Interpreted as a construction deposit and very likely late 17<sup>th</sup> century in date in service trench 3.

131 = Natural beige/pale orange clay.

132 = Culvert (covered in modern concrete), exposed in service trench 4.

133 = Deposit of compacted earth and shale in service trench 4.

134 = Compacted earth with shale inclusions (50%) in service trench 4.

135 = Natural pale grey shale grit with iron staining in service trench 4.

136 = Deposit of late 20<sup>th</sup> century midden material in service trench 2

137 = Former 19<sup>th</sup> century top soil or sub soil

138 = 19<sup>th</sup> century footpath constructed from 6 inch red quarry tiles. Appears to have formerly led to the 19<sup>th</sup> century kitchen. Service Trench 2.



1. The first part of the document discusses the importance of maintaining accurate records of all transactions and activities. It emphasizes that proper record-keeping is essential for transparency and accountability, particularly in financial matters.

2. The second part outlines the specific procedures for handling sensitive information. It states that all data must be stored securely and accessed only by authorized personnel. This section also addresses the protocols for data retention and disposal to ensure compliance with relevant regulations.

3. The third part focuses on the role of communication in organizational success. It highlights the need for clear, concise, and timely communication between all levels of the organization. This includes regular meetings, reports, and the use of various communication channels to keep everyone informed.

4. The fourth part discusses the importance of continuous improvement and innovation. It encourages the organization to regularly evaluate its processes and seek out new ways to enhance efficiency and effectiveness. This involves fostering a culture of learning and encouraging employees to share their ideas and insights.

5. The fifth part addresses the challenges of managing a diverse workforce. It provides strategies for promoting inclusivity, understanding different cultural perspectives, and resolving conflicts effectively. The goal is to create a supportive and collaborative work environment where all team members can thrive.

6. The sixth part covers the topic of risk management. It identifies potential risks to the organization's operations and outlines a systematic approach to assessing and mitigating these risks. This includes conducting regular risk assessments and implementing robust controls to prevent or minimize the impact of adverse events.

7. The seventh part discusses the importance of maintaining strong relationships with external stakeholders. It emphasizes the need for open communication and collaboration with customers, suppliers, and other key partners. Building trust and mutual understanding is crucial for long-term success.

8. The eighth part focuses on the financial health of the organization. It provides guidance on budgeting, financial reporting, and ensuring that the organization remains financially sound. This includes monitoring cash flow, managing debt, and investing wisely for future growth.

9. The ninth part addresses the legal and regulatory requirements that the organization must adhere to. It outlines the key laws and regulations that apply to the organization's operations and provides advice on how to ensure full compliance. This is essential to avoid legal penalties and maintain the organization's reputation.

10. The final part of the document provides a summary of the key points discussed and offers concluding thoughts on the overall direction of the organization. It reiterates the commitment to excellence, integrity, and sustainable growth, and expresses confidence in the organization's future.

139 = Turf and top soil in service trench 3 (ST3)

140 = Deposit of clay, sand, grit and shale with 19<sup>th</sup> century pottery fragments (ST3).


141 = Deposit of compacted beige/grey clay intermixed with crushed shale. Likely former late 17<sup>th</sup> and 18<sup>th</sup> century footpath (ST3).

142 = Deposit of crushed grey shale, intermixed with clay, ash, charcoal and lime fragments. Construction deposit (ST3).

143 = Natural beige/pale orange clay (ST3).

1. 15. 20. 40 100 200 300 400 500 600 700 800 900 1000  
 2. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20.  
 3. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20.  
 4. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20.  
 5. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20.  
 6. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20.  
 7. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20.  
 8. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20.  
 9. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20.  
 10. 1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20.

## **APPENDIX IV:** Levels Register



# Gilfach-y-Berthog

## LEVELS REGISTER

### *Levels (in meters)*

#### **Lower Parlour Room**

- 0. 0.00
- 1. -1.00.
- 2. -0.95
- 3. -0.75
- 4. -0.85
- 5. -0.80
- 6. -0.76
- 7. -0.68
- 8. -0.70
- 9. -0.62
- 10. 0.54
- 11. 0.50
- 12. 0.42
- 13. -0.53
- 14. -0.60
- 15. -0.35
- 16. -0.26
- 17. -0.25
- 18. -0.22
- 19. -0.38

#### **Trench 1 and Service Trench 1**

- 20. 0.00
- 21. 0.05
- 22. 1.12
- 23. 0.05
- 24. -1.25
- 25. 0.00
- 26. -1.46
- 27. -0.46

#### **Service Trench 2**

- 28. 0.00
- 29. -1.00
- 30. -1.75

#### **Service Trench 3**

- 31. 0.00
- 32. 0.65
- 33. -0.70
- 34. -0.10
- 35. 0.02

#### **Service Trench 4**

- 36. 0.00
- 37. -0.23
- 38. -0.88
- 39. -0.70
- 40. -0.20



# 1. Introduction

The purpose of this study is to

1.1. Objective

1.2. Scope

1.3. Methodology

1.4. Results

1.5. Conclusion

1.6. Acknowledgments

1.7. References

1.8. Appendix

1.9. Bibliography

1.10. Glossary

1.11. Index

1.12. Summary

1.13. Abstract

1.14. Introduction

1.15. Conclusion

1.16. Acknowledgments

1.17. References

1.18. Appendix

1.19. Bibliography

1.20. Glossary

1.21. Index

1.22. Summary

1.23. Abstract

1.24. Introduction

1.25. Conclusion

1.26. Acknowledgments

1.27. References

1.28. Appendix

1.29. Bibliography

**Trenches 2-7 in former timber barn**

41. 0.00  
42. 0.00  
43. -0.28  
44. 0.00  
45. -0.26  
46. 0.00  
47. -0.28







## **APPENDIX V:**

### **Archive Cover Sheet**



2001-01-10

## ARCHIVE COVER SHEET

Gilfach-y-berthog  
Abergwelli, Carmarthenshire

ARCHIVE DESTINATION – RCHAMW

|                                 |  |
|---------------------------------|--|
| Site Name:                      | Gilfach-y-berthog, Abergwelli, Carmarthenshire |
| Site Code:                      | GYB/2012/WB                                    |
| PRN:                            |  |
| NPRN :                          | N/A  |
| SAM:                            | N/A  |
| Other Ref No:                   | HRSW Report No. 131                            |
| NGR:                            | SN4813022955                                   |
| Site Type:                      | 17th Century Welsh Gentry House                |
| Project Type:                   | Watching Brief                                 |
| Project Manager:                | Richard Scott Jones                            |
| Project Dates:                  | Feb 2012 - Oct 2013                            |
| Categories Present:             | N/A  |
| Location of Original Archive:   | HRS Wales                                      |
| Location of duplicate Archives: | Dyfed Archaeological Trust                     |
| Number of Finds Boxes:          | None   |
| Location of Finds:              | NA   |
| Museum Reference:               |  |
| Copyright:                      | HRS Wales                                      |
| Restrictions to access:         | None   |



1000 1000 1000 1000 1000 1000 1000 1000 1000 1000  
 1000 1000 1000 1000 1000 1000 1000 1000 1000 1000

1000 1000 1000 1000 1000 1000 1000 1000 1000 1000  
 1000 1000 1000 1000 1000 1000 1000 1000 1000 1000

**H e r i t a g e**  
**Recording Services Wales**

HERITAGE & ARCHAEOLOGICAL  
CONSULTANTS AND CONTRACTORS

Pen-y-Fan, 11 Forest Lane, Llangybi, Ceredigion, SA48 8LZ  
Tel: 01570 493312 Fax: 08712 428171 E-mail: [richard@hrswales.co.uk](mailto:richard@hrswales.co.uk)