

Heritage.Prn: SA008

HERITAGE_I:

B_W_REGION: MID

WATERWAY: SWAN

B_W_STRUCX:

SIDE: CEN

B_W_OWNED: Y

OS_SHEET: SN 70NW

NGR:

BUILDING1: LOCK

CROSS_REFS:

COUNTY: W GLAMORGAN

LA_DISTRIC: LLIW VALLEY

PARISH_TOW: LLANQUICKE

ADDRESS_1: LOCK NO 12, YNYSMEUDWY

ADDRESS_2:

ADDRESS_3:

ADDRESS_4:

ALT_ADDRES:

ITEM004:

PHOTO_NEG: 01/16 - 19

SAM1:

DATE_LISTE:

GRADE:

SERIAL_NO:

PROTECTEDX:

STRUCS_INX:

DESIGN_INT: D

CONTEXT_1:

SETTING: B

CONTEXT_2: GRO

GROUP_VALU: N

CONDITION: D

LISTABLE_Q: N

PRESENT_US:

BUILDING_T:

DATE1:

DATE2:

DATE3: L C18

DESIGNERS:

MATERIALS: ST.

S_FEATURES:

TECH_MERIT:

RCHME:

DATE_INSPE: 30/03/96

NOTES.Prn: SA008

Dressed limestone coped stone chamber, some parts fallen away
from water control mechanism. No gates or gearing remain.

Timber hinge post remains at lower gate. Wing walls patched and
repaired with engineering brick. Stone quadrant and steps.



SA008

01/16

SA008 01/17

SA007 01/17





SA008

01/18

SA008 01/19

SA007 01/19

