F Site Notes/List or Scheduling Description

Farmhouse. MC20, possibly of earlier origins. Brick, roughcast rendered and painted grey. Pitched slate roofs. Back elevation onto canal. Main block gable end onto canal at first floor level, with horizontal wing facing canal, also one storey. Two other horizontal wings parallel to the canal, of two storeys, but first floor to canal level. Random modern casement windows with glazing bars. Front of building not inspected.

G Defects

Repairs





