

BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

219

A BW Region M+SW PRN

Waterway M+BC OS Sheet

BW Struc No NGR

Side ☒ TOW ☐ OFF ☐ CEN ☐ OTH Photo Neg No 14 / 8

BW Owned ☒ Y ☐ U/K ☐ N MMS/PMS

B County GWENT Alt Address

LA District Torfaen

Parish

Address SLVICE AT

C Date Listed SAM No

Grade	I	II*	II	Protected Area	NP	AONB	CA	SSSI
Serial No				Structures in Item				

D Design Integ A B ☒ C D Context VIL ☒ URB ☐ ISO GRO

Setting A B ☒ C D Condition A B ☒ C D

Group Value Y ☒ N

Listable Y ☒ N Present Use SLVICE

E Building Type SLVICE

Date 1) 2) 3) MLCZO

Designer(s)

Materials BR ST EBR ☒ CO IR ☒ ME WD

TI SL CTI CER AS OTH

S Features/
Tech Merit

Date Inspected 25 10 95

F Site Notes/List or Scheduling Description

Sluice. MC20. Concrete culvert, with steel safety surround. Steel drainage mechanism.

G Defects

Repairs



MB219 14/0