

BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

A	BW Region	M+SW	PRN	169
	Waterway	M+BC	OS Sheet	
	BW Struc No	BR no 78	NGR	
	Side	TOW OFF <input checked="" type="radio"/> CEN OTH	Photo Neg No	12 / 17 + 18
	BW Owned	<input checked="" type="radio"/> Y U/K N	MMS/PMS	
B	County	GWENT		
	LA District	Mammoth Torfaen		
	Parish			
	Address	BR no 78 MILL TWM BRIDGE		
C	Date Listed	SAM No		
	Grade	I II* II	Protected Area	<input checked="" type="radio"/> NP AONB CA SSSI
	Serial No	Structures in Item		
D	Design Integ	A <input checked="" type="radio"/> B C D	Context	VIL URB <input checked="" type="radio"/> ISO GRO
	Setting	A <input checked="" type="radio"/> B C D	Condition	A <input checked="" type="radio"/> B <input checked="" type="radio"/> C D
	Group Value	Y <input checked="" type="radio"/> N	Present Use	FOOTBRIDGE
	Listable	Y <input checked="" type="radio"/> N		
E	Building Type	ACCOMMODATION BRIDGE		
	Date	1) 1812 2) 3) C20 REBUILDING		
	Designer(s)	WILLIAM CROSSLEY		
	Materials	<input checked="" type="radio"/> BR <input checked="" type="radio"/> ST EBR CO IR ME WD		
		TI SL CTI CER AS OTH		
	S Features/ Tech Merit			
	Date Inspected	18 10 95		

F Site Notes/List or Scheduling Description

Accommodation bridge. c1812 with C19 and C20 renewal. William Crossley engineer. Coursed rubble sandstone. Elliptical arch with dressed stone voussoirs and prominent keystones shows signs of rebuilding especially to the northern elevation and with newer sandstone below the arch springing line. Hump-backed parapet with flat stone copings, replaced with brick in places. Slightly protruding terminating piers.

G Defects

Repairs



MB169 12/17



MB169 12/11