## F Site Notes/List or Scheduling Description

5

Boathouse. EC19, renovated LC20 into house and offices of boathire company. Coursed rubble stone with wooden frame construction. Hipped slate roof. Long rectangular plan. Two storeys. Ground storey has five openings; glazed to the left and enclosed at the right as a workshop. Central bays used for storage and workshop. First storey has six evenly spaced modern casements, and large central five-paned casement. Forms spectacular grouping with Llanfoist wharf house, in steeply wooded setting and adjacent to the site of the former Hill's tramroad.

G Defects

Repairs

