BW Region	Mtsw			PRN	179
Waterway	M +BC			OS Sheet	v - (
BW Struc No				NGR	
Side	TOW O	FF CEN	() ()	Photo Neg No	13/1
BW Owned	Y	U/K	N	MMS/PMS -	
County	GWENT			Alt Address	
LA District	Mistroo	out -	Torfaer	<b>^</b>	
Parish	· ·	-			-
Address	CANAL	COTTAC	TE + STAB	LES, GOUTRE	WHARF
Date Listed				SAM No	
Grade	1	<u> </u>  *	(1	Protected Area	NP AONB CA SSSI
Serial No				Structures in Item	-
Design Integ	A B	) с	D	Context	VIL - URB ISO GRO
		_	_	Condition	
Setting	A B	) с	D	Condition	A (B) (C) D
Setting Group Value	A (B)	) C N	D	: 	
	A B		D	Present Use -	A BOOCO B STIOP, FAULITIES, HOVSE
Group Value	Υ Υ	N _N	D TE + STABI	Present Use	STIOP, FAULITIES, HOVSE
Group Value	Υ Υ	N _N		Present Use	STIOP, FAULITIES, HOUSE 3)C19, CZO
Group Value - Listable Building Type	Y CAN AL	N _N	TE + STABI	Present Use	STIDP, FALILITIES, MOUSE
Group Value Listable Building Type Date	Y CAN AL	N _N	TE + STABI	Present Use	STIOP, FAULITIES, HOUSE
Group Value Listable Building Type Date Designer(s)	Y CAIN AL 1)		TE + STABI 2)	Present Use -	STIOP, FACILITIES, HOVSE 3)C19, CZO ANTERATIONS ME
Group Value Listable Building Type Date Designer(s)	Y CAN AL 1)		TE + STABI 2) EBR	Present Use - ES CO _IR	STIOP, FACILITIES, HOVSE 3)C19, CZO ANTERATIONS ME

\_\_\_\_\_

F Site Notes/List or Scheduling Description

> Canal cottage and stables, converted into shop, kitchen and toilet facilites. E-MC19 with later additions and alterations. Coursed rubble sandstone, rendered and painted white with a black plinth. Pitched slate and tiled roof. Two storeys. Rectangular plan; original cottage (now shop) with parallel stable extension. Front elevation; cottage has central entrance with porch, two six-paned windows to each storey, and central blind window. Stone gable chimneys, rebuilt. Left side of block is extension to the house, and has tie plate where internal wall separates house from stable. Irregularly spaced windows, LC20 casements with glazing bars. C20 rubble stone buttress adjacent to right window. Gable end shows trace of earlier segmental-arched opening, now with LC20 casement windows to ground and first storeys. Back elevation much altered, for toilet facilities.

New house built as a cross wing at left end of old cottage. Brick, tiled roof with two storeys (not inspected as private property.)

## G Defects

## Repairs

