
EXPLORATION TYWI! SITE RECORDING SHEET	
Site Name: BETWS PILL BOX PRN	1:109301
Community:  BETWS AMMANNEWS  Site Type:  PICC BOX  National Grid	•
Site Type: PICC BOY	
National Grid Reference: SN 63981 11147	
Sources: (Yes / No):	
Tithe Map OS 1 <sup>st</sup> ed OS 2 <sup>nd</sup> ed	Recent OS
Other (Please Specify):	
Date of recording:	
25/02/2012	
Recorded by:	
A.D. COOMSE	
Site Description: What does it look like? What is it made of? What do you think it is?  Any idea how old it is?	
Type 24 Wold War 2 Pill Box. IRREGULAR HEXAGON	
Type 24 Wold War 2 Pill Box, TRAFFORIAR HEXAGON Shuttered concrete construction, EVIDONG OF WOOD SANTTORING	
ON ALL WALLS AND ROOF.	
ENTRANCE FACES ARGOTED ROAD BETWI.	
SITE NOW CIVERED IN SCRUB WOODLAND WATCH APPEARS	
TO POST DATE SOROND WORLD WAR	
INIORIAR PARTUGRAPHS), NOT CX AM: NOD, AS BNIRANCE	
CAR AID SMARL.	
THORE IS NO EVIDENCE OF ANY CATINGS ASSOCIATED	D WI. IT
SOORWAY OR EMBRASINEST	
Photo Record No:	
Site Condition: Is it in good condition / fair / poor / damaged	
G 500	
Site Threats:	
TREE TRUNK ABUTTING SOM A KAST FARCE	S



Tywi a River Through Time is part funded by Heritage Lottery Fund, Countryside Council for Wales, Rural Development Plan, Welsh Assembly Government, Carmarthenshrie County Council and in kind by The National Trust

WWZ PILL BOX ARGOED ROAD, BETWS. (SOUTH SIDE)

GRID REF SN 6398/11147

GRID REF SN 6398/11147

IRREGULAR HEXAGON

CONSTRUCTION

BARE CONCRETE

ShUTTERING MARKS CLEARLY VISIBLE

NO DISCERNIBLE INTERNAL DIVISION/WALL

NOT ENTERED BECAUSE OF STEEP

SLIPPERY SLOPE AND SMALL

ENTRANCE:

CONDITION

APPEARS COMPLETE NO SIGNIFICANT DAMAGE

ROOF NOT EXAMINED IN DETAIL AS
COVERED BY 500m of ACCUMULATED
VEGETATION DEBRIS

FLOOR NOT EDAMINED SOME LITEER AND MUCH VEGITATION DEBRIS SURROUNDED BY SCRUB WOODLAND

CNE L'ARGE TREE ABUTTINGE EAST FACING WALL WITH ROOTS PROBABLY WIDERNEATH

## NORTH FACE (ENTRANCE FROM ARGOED ROOD BETWS)

