

BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

157

A	BW Region	M+SW			PRN					
	Waterway	M+BC			OS Sheet					
	BW Struc No	BR NO 86			NGR					
	Side	TOW	OFF	<input checked="" type="radio"/> CEN	OTH	Photo Neg No	10 / 10 + 11			
	BW Owned	<input checked="" type="radio"/> Y	U/K	N	MMS/PMS					
B	County	GWENT				Alt Address				
	LA District	Monmouth								
	Parish									
	Address	BR NO 86, OCHLAN TURN BRIDGE								
C	Date Listed					SAM No				
	Grade	I	II*	II	Protected Area	<input checked="" type="radio"/> NP	AONB	CA	SSSI	
	Serial No					Structures in Item				
D	Design Integ	A	B	<input checked="" type="radio"/> C	D	Context	VIL	URB	<input checked="" type="radio"/> ISO	GRO
	Setting	A	<input checked="" type="radio"/> B	C	D	Condition	A	<input checked="" type="radio"/> B	C	D
	Group Value	Y	<input checked="" type="radio"/> N					FOOT BRIDGE		
	Listable	Y	<input checked="" type="radio"/> N					Present Use		
E	Building Type	ACCOMMODATION BRIDGE								
	Date	1) 1812				2)	3) REBUILT 1820			
	Designer(s)									
	Materials	BR	<input checked="" type="radio"/> ST	EBR	CO	IR	<input checked="" type="radio"/> ME	<input checked="" type="radio"/> WD		
		TI	SL	CTI	CER	AS	OTH			
	S Features/ Tech Merit									
	Date Inspected	17 10 95								

F Site Notes/List or Scheduling Description

Accommodation bridge. c1812 with LC20 rebuilding. Coursed rubble sandstone abutments, rebuilt to support steel and wooden deck. Tubular steel handrails, painted black and white.

G Defects

Repairs



MB157 10/10

