

Historic Environment Feature Management Report:

Lime kiln At Bowett Farm

Customer Reference Number: A0031495

UID: 300612



©DAT 2002

This management plan has been produced by Dyfed Archaeological Trust Heritage Management to inform the positive management of the identified Priority Historic Environment Feature. The identified management outcome will meet the objective for the Historic Environment Feature Targeted Layer as part of the Glastir Land Management Scheme.

PRN 17903 Name

Period Post-medieval **Site Type** Lime kiln

NGR SM 9601 7866

Status Listed Building Grade II

Site Description

A lime kiln recorded on the 1889 Ordnance Survey map as O K (old kiln) indicating abandonment.

It survives as a square, stone-built structure, with opposing draw holes, access ramp and in-situ brick lining. A field visit in 2002 recorded the structure as near complete but being overgrown with intrusive vegetation and ivy (Pyper).

The structure is depicted on the most recent Ordnance Survey mapping (Mastermap 2011) as Kiln Disused.

Management Issues

The main management issue for this site is the control of intrusive vegetation which has the potential to damage built structural remains by the prising apart of masonry bonds.

Desired Management Outcome

The desired management outcome is to reduce further degradation of the built structural remains and to keep them in a stable condition.

Management Actions

The following management actions are required in order to keep the structure in a stable condition:

- Cut back any ivy and vegetation in order to retain the visibility of the structure.
- Remove any young trees growing out of the top of the structure by cutting by hand. Do not pull-up by the roots as this is potentially destabilising to masonry bonds. Cut any scrub back by hand. Spot treat to prevent re-growth.
- Carry out a programme of masonry consolidation and re-pointing in order to make the structure safe. Contact Dyfed Archaeological Trust for further advice.

Note:


This is a listed building therefore guidance and consent is required from the local authority historic building conservation officer for any works to the fabric of the building.

Location Map



Historic Environment Feature (UID 300,612)

Detail from the 1st edition Ordnance Survey map (1889)



© and database right Crown copyright and Landmark Information Group Ltd (All rights reserved 08/05/2012)



Historic Environment Feature (UID 300,612)

PHOTOGRAPHS



© Next Perspectives. Welsh Assembly Government 2009



PRN 17903 Damage to corner © DAT 2002



PRN 17903 Charging ramp from SW. © DAT 2002



PRN 17903 Ivy over structure from north east © DAT 2002

Maps based upon Ordnance Survey material with the permission of Ordnance Survey on behalf of the Controller of Her Majesty's Stationery Office Crown copyright. Unauthorised reproduction infringes Crown copyright and may lead to prosecution or civil proceedings'. Welsh Assembly Government 100017916.
[02.28.13](#)

Archaeological data, from the Regional Sites and Monuments Record, supplied by The Dyfed Archaeological Trust in partnership with Local Authorities, Cadw and the partners of ENDEX DAT, 2011 (and in part Crown, 2011).

[28.02.13](#) - HTML file produced for Glastir management report, DAT file number [360](#).
Dyfed Archaeological Trust, Heritage Management, The Shire Hall, 8 Carmarthen Street, Llandeilo,
Carmarthenshire SA19 6AF.
tel (01558) 823131 , fax (01558) 823133, email info@dyfedarchaeology.org.uk , website
www.dyfedarchaeology.org.uk