

Part of Stacky Estate.

Sawmill (1850) good condition. 2 storey, cut stone, stone quoins. Brick voussiors. Gabled roof. Partile roof. Front elevation = 2 single doorways; 1 double doorway with circular window above. 2 windows between single doors: leaded. Side elevation north = large sliding door windows either side (lattice).

Rear elevation: large sliding door with tracks leading in above circular window. Sawmill still in use. waterwheel in good condition.

Carpenter's workshop and cartshed. 1850's.


Roof, and floors, walls in bad repair. Partiles.

2 storey with 4 windows above 4 cart arches with brick voussiors. Cart shed on ground floor, carpenter's workshop on 2nd floor. Bank barn type with access to 2nd storey from bank at rear.

3 storey tower section on left side next to smithy, without roof and in disrepair.

Smithy

Apexing tower section of cartshed/carpenter workshop. Single storey. Partile roof. Front elevation: 2 doors on left with brick voussiors. Probably 2 cart arches to right, now altered and used as garage/workshop.



AM Feb 28. 1985