

COMMENT

Main structure of mill rectangular in shape with adjoining square 1 1/2 storey building. The wheel housing was originally situated outside the SW wall which has aperture for the wheel axle and a water gate at its base. Building was 3 storey, evidence of third floor level: high windows. 2nd level: timber floors with door from mill into adjoining building and other to rear of mill. Irregular cut stone construction with stone quoins / lime mortar, building is roofless with some remaining timbers on eastern building. Churny beams? at NW and SE ends, possibly bell cote (?) Mill is overgrown and walls covered with ivy. Interior of mill filled with debris.

AUTHORITY

AD 25/3/85

