

According to the farmer, John Gibson,
This was a farmstead. A large enclosed
area surrounded by high banks with
a rough deeply worn trackway running
from field entrance W $\rightarrow$ E.

Ruin of several buildings/cottages.
The ruin of a chapel? barn? sited
near the centre of the enclosed area,
rubble stone construction, lime mortar,
with ventilation slits? low on walls
and long arched window facing South.
South and North walls standing to
approx full height (1½ storeys) of previous
roof (no remains of roof).

Walls West & East standing to height
of approx 1m.

Cottage? adjoining South wall.

Other wall remains in NE of enclosure,
and SW.

AM/11/4/85

