


COMMENT

AUTHORITY

NANT SAWS

Single Storey stone built
Post medieval dwelling. in a bad state
of disrepair. asbestos roof and a brick
chimney walled enclosure around the house.
Part of the roof has collapsed.

NANT SAWS.

A. S. Maull
JAN 1984.