

## COMMENT

IA AUTHORITY

- SN 115449 - shaft in field above sewage treatment plant, capped after unsuccessful attempt to fill it in 1940-42. Apparently spoil heap was in evidence prior to construction of sewage plant. Mineral sought not known. No documentary evidence.

P.F. CLAUGHTON  
1990

1. Name - Not Known                      Grid ref. SN 115449  
Parish - Moylegrove                      Distriot - Preseli Pembs.  
Shaft in field on southwest side of Cwm Trewyddel, above sewage treatment works.  
No surface features remain; filled 1940-45.  
No historical detail available.

PF CLAUGHTON  
1991