

COMMENT


Several Phases of construction
chancel + nave ①

roofline different.

Tower massive,

catalanized

Gravestones - in general
only good condition.



Ref: Belfry - Double, secondary - earlier one below.

CMS 9.5-85

AUTHORITY