

rough cast, 3 storey, slate roof, Modillion
cornice, 19c window sashes. 1/2-glazed
door. 3 storey wing.

Slate roof, rendered stacks

chamfered quoins, symmetrical 3 storey 7-window
frontage. Centre portion 5 windows, breaks
forward slightly & has modillioned pediment.

Sunken oval panel in 4-keyed frame with
cross motif in relief to tympanum.
Windows are 19th sashes, in reveals to
1st & 2nd floors French windows to ground
floor. Central half-glazed double doors,
portico with flat entablature on 4
paired Doric columns. Full height
semi-circular bow with conical slate
roof & sash windows to right-hand end
elevation, 3 storey one window wing
set back to left hand. Interior may be
of interest.

OUTLYING ITEM

II Cilgwyn House

7113

C18. Rough-cast, slate roof, rendered
stacks, modillion eaves cornice,
chamfered quoins. Symmetrical 3-
storey, 7-window frontage, centre portion
(5 windows) breaks forward slightly and
has modillioned pediment, sunken oval
panel in 4-keyed frame with cross motif
in relief to tympanum. Windows are
C19 sashes in reveals to first and second
floors, French windows to ground floor.
Central 1/2-glazed double doors under
portico with flat entablature on 4
(paired) Doric columns. Full-height
semi-circular bow with conical slate
roof and sash windows to right-hand end
elevation, 3-storey 1-window wing set
back to left-hand. Interior may be of
interest.