



Aberporth ROC Post

Dyfed

REPORTS IMAGES VIDEOS MAP

Written by Unknown on 19 July 2003.

On a mound the north side of an un-named minor road next to some wooden stables

OPEN All surface features remain intact although the top of the ventilation shaft adjacent to the access shaft is missing as are all the ventilation louvres. The step is also detached. The FSM pipe is encased in concrete. The hatch is open although the hinge has seized making it is difficult to lift. The original locking bar is still in place. Internally the following artifacts remain: shelf, cupboard, chair, single bed, watering can, oil lamp and one mattress.

Opened in 1960 and closed in 1968.

1 of 1 30/03/2021, 14:28