



Fishguard ROC Post

Dyfed

[REPORTS](#)

[IMAGES](#)

[VIDEOS](#)

[MAP](#)

Written by Unknown on 19 July 2003.

On a mound in the south west corner of a field close to a trig. Station on a hilltop, 150 yards west of a communications mast on the west side of an unnamed minor road.

OPEN All surface features remain intact but there is some damage to the top of the ventilation shaft. The top of the other ventilation shaft (adjacent to the access shaft) is missing as are all the ventilation louvres. There is also a little damage to the top of the access shaft. The concrete apron around the access shaft is badly cracked. Some of the compound fence posts lie in the grass nearby, others have been dropped down the shaft. Internally the post has been stripped with only 2 chairs remaining.

Opened in 1963 and closed in 1968.
