



Llandyssul ROC Post

Dyfed

REPORTS

IMAGES

VIDEOS

MAP

Written by Unknown on 21 May 2002.

10 yards east of the A486 and on the north side of a field boundary.

OPEN All surface features remain intact. The GZI mount is detached and lying on the ground. The ventilation louvres are missing. The hatch is open. Internally the monitoring room is clean and dry and free of any vandalism. Remaining artefacts include twin bunks, single bed, table, shelf, cupboard, net, rope, large splint, newspaper from 1967, GPO junction boxes and wiring and a large splint.

An Orlit B in good condition stands between the post and the road.

Opened in 1960 and closed in 1968.
