

ROC MUSEUM - POST VISIT FORM.

Post Name CROSSWOOD Final Desig: 13/10 Date of Visit 07/09/00 Time 14:20

Location Guide to site: TOP OF GRASS FIELD ALONGSIDE HEDGE & UNUSED TRACK UP FROM ROAD
Description LEADING PAST SCHOOL. TRACK HAS MINISTRY GALVANISED GATE

Geog of Area: NARROW & WOODED VALLEY

Orientation of U/G Post: S = DD- (eg AA-BB)

Horizon/panorama: HIGH HILL TO NE - OTHERS LOWER & MORE DISTANT.

Type of Post: U/G; ORLIT 'A'; ORLIT 'B'; A/G Other;

Master: Recent/Past; Non Master: ☐ Closure: 1992/Earlier/1968/Earlier

Post Status: Intact ☒ Partly demolished ☐ Removed ☐ Not found ☐

Site: Flat ☐ Mounded ☒ Slight ☐ Medium ☐ Heavily ☒ Steps ☒ Paving

Shape: ☐ ☐ ☐ ☐ ☐ Large/medium/small

NO FENCING - 5YDS IN FROM HEDGE - POLES UP FROM ROAD

Surface/vegetation: LONG GRASS

Fencing: None: ☒ Gates: 1,2 Style:

Entrance:

Condition of Post: NEW GALVANISED HATCH EXTERNAL HATCH ALMOST TOO LARGE OVERLAPPED AT 1-4

Entrance Turret WITH EXTERNAL HINGES Hatch: Type

Hatch hinged: 1-2, 2-3, 3-4, 4/1 Keyhole type: 4 K/H ☒ over

Steps: A ☐ B ☐ C ☒ none ☐ single/double, Not solid: ☐

Turret profile: square/chamfered (round/squared)

Ventilators: raised/flush, metal/wooden, No of slats: 5 None: ☐ Y ☐ N

condition: SOME RUST - PAINT LT GREEN EXCELLENT.

Ventilator Turret LT GREEN EXCELLENT

Top Type: Flat ☐ Domed ☐ Hipped ☐ Pitched A/C, B-D Square/oblong
Sloping A-C, C-A, B-D, D-B.

Ventilators: None ☐ Wooden ☐ Metal ☒ Box/flush ☐ No of Slats 5

Surfaces: Painted EXCELLENT LT. GREEN Crumbling/damage -

Security: Locks: 1/2/0 Hasps: 1/2/0 Locking Bar ☐ Y ☐ N Lckng Bar Locations: ☐ Y ☐ N

Master equipment: 2 CHUBBS & LARGE COVERS

at 2 & 3 CORNERS

Details of A/G Post on site: CONNECTIONS COVER & MAST BOARD IN PLACE.

Operational equipment on site: CONCRETE SURROUND BADLY CRACKED

BPE PIPE HAS CONCRETE BASE. GZE ON RAISED BASE

Non-standard features: CUT-OUT BASE OF VENTILATOR FOR AERIAL

FSM PIPE CIRCULAR CONCRETE BASE - PLAIN TOP LOCATED WITH PINS

Post Personnel known:

