

ROC MUSEUM - POST VISIT FORM.

Post Name DRYSLWYN Final Desig: 13/45 Date of Visit 06/03/00 Time 17:30

Location Guide to site: ALONGSIDE BYE ROAD - 3 STEPS & LOCKED GATE FROM ROAD.

Description TO 'S' OF ROAD RUNNING 'E' FROM WERN GARAGE ON A40.

Geog of Area: FAIRLY HILLY - FENCED PASTURE FIELDS

Orientation of U/G Post: S = AA-BB (eg AA-BB)

Horizon/panorama: VERY GOOD DISTANCE EXCEPT HEDGE TO 'N' BUT GOOD BEHIND IT.

Type of Post: U/G; ORLIT 'A'; ORLIT 'B'; A/G Other;

Master: Recent/Past; Non Master: ☐ Closure: 1982/Earlier/1968/Earlier

Post Status: Intact ☒ Partly demolished ☐ Removed ☐ Not found ☐

Site: Flat ☐ Mounded ☒ Slight ☐ Medium ☐ Heavily ☒ Steps/Paving

Shape: ☐ ☐ ☐ ☐ ☐ Large/medium/small

NO FENCING EXCEPT.

Surface/vegetation: GRAZED GRASS

Fencing: None ☒ Gates: 0,1,2 Style:

Entrance: PERSONNEL GATE - LAY BY TO 'W' ALONG ROAD

Condition of Post:

Entrance Turret VERY SOUND - 2 CHUBBS LOCKED VERTICAL GREEN - SOME CRACK ALONGSIDE VENT AT '2' Hatch: RUST PATCHES Type * STD PATTERN

Hatch hinged: 1-2, 2-3, 3-4, 4/1 Keyhole type: L K/H Cover

Steps: A ☐ B ☐ C ☒ none ☐ single/double, Not solid: ☐

Turret profile: square/chamfered (round/square)

Ventilators: raised/flush, metal/wooden, No of slats: 7 None: Y N

condition: WEATHERED GREEN - VERY SOUND - SURROUND CRACKED AND SOME SUBSIDENCE.

Ventilator Turret

Top Type: Flat ☐ Domed ☐ Hipped ☐ Pitched A/C, B-D Square/oblong
Sloping A-C, C-A, B-D, D-B.

Ventilators: None ☐ Wooden ☐ Metal ☒ Box/flush ☐ No of Slats 7

Surfaces: Painted WEATHERED LT GREEN Crumbling/damage NE CORNER KNOCKED OFF.

Security: Locks: 1/2/0 Hasps: 1/2/0 Locking Bar Y/N Lckng Bar Locations: Y/N

Master equipment:

CONNECTION COVER, MAST BOARD & LIGHTNING CONDUCTOR

Details of A/G Post on site: NONE

Operational equipment on site: VERY SHORT BPI PIPE, TALL FSM PIPE.

TELEGRAPH POLES ALONG ROAD FROM 'W'

Non-standard features: STUDDED FSM PIPE COVER

Post Personnel known:

