

ROC MUSEUM - POST VISIT FORM.

Post Name LAMPETER Final Desig: 13/25 Date of Visit 06/03/00 Time 12:15

Location Guide to site: HEAD OF OPEN VALLEY TO SW. SMALL ROC GATE AT ROADSIDE LEADING TO GATE
 Description AT TOP OF FIELD WITH POST UP ON RIGHT. ROAD RUNNING OFF A482 BESIDE COOP SUPERSTORE.

Geog of Area: SMALL FIELDS, VERY WINDING ROADS. MOSTLY GRAZING.

Orientation of U/G Post: S = DD-CC (eg AA-BB)

Horizon/panorama: AGAINST SHOULDER OF HILL TO 'N' BUT GOOD HORIZONS W, S & E.

Type of Post: U/G; ORLIT 'A'; ORLIT 'B'; A/G Other;

Master: Recent/Past; Non Master: ☐ Closure: 1992/Earlier/1968/Earlier

Post Status: Intact ☒ Partly demolished ☐ Removed ☐ Not found ☐

Site: Flat ☐ Mounded ☒ Slight ☐ Medium ☒ Heavily ☐ Steps/Paving ☒

Shape: ☐ ☒ ☐ ☐ ☐ Large/medium/small ☒

GATE TOP OF FIELD AGAINST FENCE 1/2 'N' END

Surface/vegetation: LONG GRASS, TWO ODD BUSHES.

Fencing: None: ☐ Gates: OUT, 2 Style: 6' CONCRETE / LINK & 3 STRANDS BARBED

Entrance: PERSONNEL GATE, SQUARE METAL TUBING - VERY SOLID & SECURE - YALE SECURITY LOCK + BARBED OVER.

Condition of Post:

Entrance Turret WEATHERED BUT SOUND Hatch: LOCKED Type ? STD

Hatch hinged: 1-2, 2-3, 3-4, 4-1 Keyhole type: NOT VISIBLE K/H COVER?

Steps: A ☐ B ☐ C ☒ none ☐ single/double, Not solid: NOT FULL WIDTH

Turret profile: square/chamfered (round/squared) ☒

Ventilators: raised/flush, metal/wooden, No of slats: 7 None: Y N
 condition: GALVANISED

Ventilator Turret

Top Type: Flat ☒ Domed ☐ Hipped ☐ Pitched A-C, B-D Square/oblong
 Sloping A-C, C-A, B-D, D-B.

Ventilators: None ☐ Wooden ☐ Metal ☒ Box/flush ☐ No of Slats 7

Surfaces: Painted WEATHERED BUT SOUND Crumbling/damage NONE VISIBLE

Security: Locks: 1/2/0 Hasps: 1/2/0 Locking Bar Y/N Lckng Bar Locations: Y/N

Master equipment: CONNECTION COVER IN PLACE.

Details of A/G Post on site:

Operational equipment on site: LIGHTNING CONDUCTOR STRIP STILL OK.

Non-standard features: STUDDED FSM PIPE COVER

Post Personnel known:

