

ROC MUSEUM - POST VISIT FORM.

Post Name LAUGHARNE Final Desig: 13/41 Date of Visit 05/09/00 Time 10:40
 Location Guide to site: FAR CORNER OF FIELD DIAGONALLY ACROSS FROM SIR JOHN'S HILL FARM
 Description ON EDGE OF ESCARPMENT.
 Geog of Area: COASTAL, QUITE HILLY.
 Orientation of U/G Post: S = AA-BB (eg AA-BB) (NEARER AA)
 Horizon/panorama: ?(MISTY)

Type of Post: U/G; ORLIT 'A'; ORLIT 'B'; A/G Other;
 Master: Recent/Past ; Non Master: ☒ Closure: 1992/Earlier/1968/Earlier
 Post Status: Intact ☒ Partly demolished ☐ Removed ☐ Not found ☐
 Site: Flat ☐ Mounded ☒ Slight ☐ Medium ☒ Heavily ☐ Steps/Paving
 Shape: ☐ ☐ ☐ ☒ ☐ Large/medium/small
ORLIT PLATFORM

Surface/vegetation:
 Fencing: None: ☐ Gates: 0,1,2 Style: SHEEP + 2 BARBED WIRE + WOODEN POSTS
 Entrance:
 Condition of Post:

Entrance Turret SOUND LT GREEN Hatch: SOUND Type STD. PATTERN
 Hatch hinged: 1-2, 2-3, 3-4, 4-1 Keyhole type: □ K/H Xover
 Steps: A ☐ B ☐ C ☒ none ☐ single/double, Not solid: ☐
 Turret profile: square/chamfered (round/squared) SLIGHT.
 Ventilators: raised/flush, metal/wooden, No of slats: 4 None: Y N
 condition: RUSTY & HANGING OFF - HEAVY DUTY.

Ventilator Turret
 Top Type: Flat ☒ Domed ☐ Hipped ☐ Pitched A-C, B-D Square/oblong
 Sloping A-C, C-A, B-D, D-B. SMALL
 Ventilators: None ☐ Wooden ☐ Metal ☒ Box/flush ☐ No of Slats 4
 Surfaces: Painted LT GREEN, QUITE GOOD Crumbling/damage
 Security: Locks: 1|2|0 Hasps: 1|2|0 Locking Bar Y/N Lckng Bar Locations: Y/N
 Master equipment: NONE HATCH FRAME

Details of A/G Post on site: PARTLY DEMOLISHED ORLIT - PANELS ON GROUND
PLATFORM STILL THERE + 4 ORIGINAL RUNGS. TOP 3 RUNGS OF WOODEN
 Operational equipment on site: SURROUND GOOD - CHAMFER ROUND BASE. STAIRCASE - REST ON GROUND.

Non-standard features: BPI PIPE ENCASED IN CONCRETE - LARGE TOP - NOT FIXED - LOCATED BY TWO PINS

Post Personnel known:

