

ROC MUSEUM - POST VISIT FORM.

Post Name LLAN BOJDY Final Desig: 13/42 Date of Visit 03/09/00 Time 11:50

Location Guide to site: CORNER OF MEADOW IN SECOND MEADOW (HORSES) FROM MINOR ROAD
Description VERY HIGH POINT.

Geog of Area: VALLEY ALL ROUND, WIND FARM TO'S' - LONG HORIZON WAS ESPECIALLY,
ELSE SHORT HEDGES.

Orientation of U/G Post: S = AA-DD (eg AA-BB)

Horizon/panorama: 360°, SHORT FENCE TO E&S BUT BELOW GZI HEIGHT

Type of Post: ☒ U/G; ☐ ORLIT 'A'; ☐ ORLIT 'B'; ☐ A/G Other;

Master: Recent/Past ; Non Master: ☒ Closure: 1992/Earlier/1968/Earlier

Post Status: Intact ☒ Partly demolished ☐ Removed ☐ Not found ☐

Site: Flat ☐ Mounded ☒ Slight ☐ Medium ☒ Heavily ☐ Steps/Paving

Shape: ☐ ☐ ☐ ☐ ☐ Large/medium/small

UNFENCED - IN HORSE MEADOW

Surface/vegetation: GRAZED

Fencing: None: ☒ Gates: 0,1,2 Style: _____

Entrance: _____

Condition of Post:

Entrance Turret UNPRIMED 4" HOLE CUT IN HATCH Hatch: RUSTY Type # STD TYPE

Hatch hinged: 1-2, 2-3, 3-4, 4-1 Keyhole type: ? K/H ☒ Over

Steps: A ☐ B ☐ C ☒ none ☐ single/double, Not solid: ☐

Turret profile: square/chamfered (round/squared)

Ventilators: raised/flush, metal/wooden, No of slats: 5 None: ☐ Y ☐ N

condition: GOOD, PAINTED. GZI MOUNT TOP ON GROUND

Ventilator Turret ? TOP OFF & ON GROUND

Top Type: Flat ☐ Domed ☐ Hipped ☐ Pitched A-C, B-D Square/oblong

Sloping A-C, C-A, B-D, D-B.

Ventilators: None ☐ Wooden ☐ Metal ☒ Box/flush ☐ No of Slats 5

Surfaces: Painted UNPAINTED Crumbling/damage TOP OFF - ELSE SOUND

Security: Locks: 1 ☒ 0 Hasps: 1 ☒ 0 Locking Bar Y/N Lckng Bar Locations: Y/N

Master equipment: NONE

Details of A/G Post on site: NONE

Operational equipment on site: NONE - NO POSTS

Non-standard features: FSM PIPE ENCASED IN CONCRETE - TOP AS FOR LAUGHARNE

BPI PIPE ENCASED ALSO IN CONCRETE.

Post Personnel known:

