

ROC MUSEUM - POST VISIT FORM.

Post Name LLANDOVERY Final Desig: 13/47 Date of Visit 05/03/99 Time 16:15

Location Guide to site: ON RIGHT JUST INSIDE STONEBUILT GATEWAY TO THE TOWN ON ROAD FROM LLANDOVERY TO CILCHEM?

Description Geog of Area: FAIRLY LEVEL PLAIN SURROUNDED BY ROLLING HILLS

Orientation of U/G Post: S = DD-CC (eg AA-BB)

Horizon/panorama: 360° - INDIVIDUAL TREES IN PARK-LIKE SETTING.

Type of Post: ☒ U/G; ORLIT 'A'; ORLIT 'B'; A/G Other;

Master: Recent/Past ; Non Master: ☒ Closure: 1992/Earlier/1968/Earlier

Post Status: Intact ☒ Partly demolished ☐ Removed ☐ Not found ☐

Site: Flat ☐ Mounded ☒ Slight ☒ Medium ☐ Heavily ☐ Steps/Paving

Shape: ☐ ☐ ☐ ☐ ☐ Large/medium/small

NEW WOODEN POST & RAIL SHEEP & BARBED WIRE FENCE. HARD WOOD & EVERGREEN

Surface/vegetation: SHRUBS PLANTED ROUND 8-SIDED COMPOUND

Fencing: None: ☐ Gates: 0,1,2 Style: (SEE ABOVE)

Entrance:

Condition of Post:

Entrance Turret SOUND - HASPS OK - SHUT BUT LOCKS NOT DONE UP. WARTCAGEN. Hatch: SURFACE RUST Type ☒ STD. PATTERN. BUT COP. TYPE KEY COVER

Hatch hinged: 1-2, 2-3, 3-4, 4-1 Keyhole type: NOT VISIBLE K/H Cover ☒

Steps: A ☐ B ☐ C ☒ none ☐ single/double, Not solid: ☐

Turret profile: square/chamfered (round/squared)

Ventilators: raised/flush, metal/wooden, No of slats: 8 None: ☐ Y ☐ N

condition: FAIRLY SOUND - CRACK ROUND BENEATH CHAMFER. SURROUND GOOD.

Ventilator Turret

Top Type: Flat ☐ Domed ☒ Hipped ☐ Pitched A-C, B-D ☒ Square/oblong
Sloping A-C, C-A, B-D, D-B.

Ventilators: None ☐ Wooden ☐ Metal ☒ Box/flush ☐ No of Slats 8

Surfaces: Painted SHINY LIGHT GREEN OK - WEATHERED Crumbling/damage NONE

Security: Locks: 1/2/0 Hasps: 1/2/0 Locking Bar ☒ Y/N Lckng Bar Locations: ☐ Y/N

Master equipment: NONE

Details of A/G Post on site: NONE

Operational equipment on site: NONE - 2 ODD BROKEN CONCRETE POSTS IN CORNER BY GATEWAY TELEGRAPH POLE BETWEEN POST & ROADSIDE FENCE.

Non-standard features: NONE (STUDDED FSM PROBE PIPE COVER)

Post Personnel known:

