

ROC MUSEUM - POST VISIT FORM.

Post Name MARN CLOCHOG Final Desig: 13/30 Date of Visit 05/09/00 Time 13:20

Location Guide to site: AT 'S' SIDE OF ROUGH HILLTOP PASTURE BESIDE BANK

Description Geog of Area: VERY HILLY ESPECIALLY TO 'N' & 'NE' - LARGE MAST TO WEST.

Orientation of U/G Post: S = DD-CC (eg AA-BB)

Horizon/panorama: 360° SUPERB - VU DISTANT ACROSS VALLEYS - BEST VIEW TO WEST
HIGHER GROUND TO NORTH

Type of Post: U/G; ORLIT 'A'; ORLIT 'B'; A/G Other;
Master: Recent/Past; Non Master: ☐ Closure: 1992/Earlier/1968/Earlier

Post Status: Intact ☒ Partly demolished ☐ Removed ☐ Not found ☐

Site: Flat ☐ Mounded ☒ Slight ☐ Medium ☒ Heavily ☐ Step/Paving

Shape: ☐ ☒ ☐ ☐ ☐ Large/medium/small
DIPLOLE MAST & SUN PANEL ON CONCRETE
AT 'E' END OF SITE, WHIP AERIAL ON GZI MOUNT, WIND GENERATOR ON BPI PIPE

Surface/vegetation: LONG ROUGH GRASS & WEEDS. GRAY

Fencing: None: ☐ Gates: 0, 1, 2 Style: GATE ANGLE IRON FRAME & WIRE.

Entrance: 4 CONCRETE & CHAIN LINK GALVANISED - INTACT.

Condition of Post: RAISED TYPE WITH 2 LARGE EXTERNAL HINGES AT 1-4 - LOCKED AT 2-3.

Entrance Turret GRAY - NEWLY PAINTED Hatch: Type

Hatch hinged: 1-2, 2-3, 3-4, 4 Keyhole type: + K/X Cover

Steps: A ☐ B ☐ C ☒ none ☐ single/double, Not solid: ☐

Turret profile: square/chamfered (round/squared) ROUGH TOP.

Ventilators: raised/flush, metal/wooden, No of slats: 5 None: Y N

condition:

Ventilator Turret

Top Type: Flat ☐ Domed ☐ Hipped ☒ Pitched A-C, B-D Square/oblong
Sloping A-C, C-A, B-D, D-B.

Ventilators: None ☐ Wooden ☐ Metal ☒ Box/flush ☐ No of Slats 5

Surfaces: Painted ONLY TURRET PAINTED. OTHERS BARE Crumbling/damage

Security: Locks: 1 2 0 Hasps: 1 2 0 Locking Bar Y/N Lckng Bar Locations: Y/N

Master equipment: CONNECTION COVER & LIGHTNING CONDUCTOR OK

Details of A/G Post on site: NONE

Operational equipment on site: NONE. TELEGRAPH POLES STILL THERE UP FROM 'E'

Non-standard features: FSM PIPE ENCASED IN CONCRETE

BPI PIPE NOT FOUND

Post Personnel known:

