

ROC MUSEUM - POST VISIT FORM.

Post Name NEWCASTLE EMLYN Final Desig: 13/20 Date of Visit 06/09/00 Time 16:00

Location Guide to site: CORNER OF ROADSIDE MEADOW, 20 YARDS INTO LEVEL FIELD FROM FARM ROAD - ROADSIDE GATE, THEN WIRE, THEN POST GATE.

Description Geog of Area: ROLLING HILLS & VALLEYS - FARMED

Orientation of U/G Post: S = AA-BB (eg AA-BB)

Horizon/panorama: S & W VERY DISTANT HILLS. HEDGES N & E & FARM TO N

Type of Post: U/G; ORLIT 'A'; ORLIT 'B'; A/G Other;

Master: Recent/Past; Non Master: ☐ Closure: 1992/Earlier/1968/Earlier

Post Status: Intact ☒ Partly demolished ☐ Removed ☐ Not found ☐

Site: Flat ☐ Mounded ☒ Slight ☐ Medium ☒ Heavily ☐ Steps/Paving

Shape: ☒ ☐ ☐ ☐ ☐ Large/medium/small

Surface/vegetation:

Fencing: None: ☐ Gates: 0, 2 Style: VEHICLE WIDTH 3-BAR + MESH, OPENS, GALVANISED

Entrance: NEW HATCH - 2 LARGE EXTERNAL HINGES AT 1-4 - LOCKS EITHER END AT 2-3. CHUBBS IN LARGE COVERS

Condition of Post:

Entrance Turret PAINT FADED, WEATHERED Hatch: NEW TYPE Type GALV. 1-1-1 NEW TYPE PATTERAN

Hatch hinged: 1-2, 2-3, 3-4, 4-1 Keyhole type: ☒ K/H ☒ Cover

Steps: A ☒ B ☐ C ☒ none ☐ single/double, Not solid: A - METAL STEP ON 2 UPRIGHTS

Turret profile: square/chamfered (round/squared)

Ventilators: raised/flush, metal/wooden, No of slats: 7 None: Y N condition: SOLID

Ventilator Turret

Top Type: Flat ☐ Domed ☐ Hipped ☐ Pitched A-C, B-D Square/oblong Sloping A-C, C-A, B-D, D-B.

Ventilators: None ☐ Wooden ☐ Metal ☒ Box/flush ☐ No of Slats 8

Surfaces: Painted FADED, WEATHERED Crumbling/damage SOLID

Security: Locks: 1/2/0 Hasps: 1/2/0 Locking Bar Y/N Lckng Bar Locations: Y/N

Master equipment: CONNECTION COVER. BOARD FOR MAST

Details of A/G Post on site:

Operational equipment on site: ROADSIDE POLE. FENCE 4 FT. WIRE & CONCRETE POSTS

Non-standard features: CUT OUT IN LIP OF VENTILATOR TURRET.

Post Personnel known:

