

ROC MUSEUM - POST VISIT FORM.

Post Name NEWPORT (PEMBS) Final Desig: 13/C1 Date of Visit 06/09/00 Time 11:10
(N046391)

Location Guide to site: BESIDE B487 IN PASTURE OVERLOOKING BAY.
Description

Geog of Area: COASTAL HILLY COUNTRY.

Orientation of U/G Post: S = AA- (eg AA-BB)
Horizon/panorama: HILLY TO 'S'; N&E & W GOOD HORIZON ALONG COAST; NW OPEN SEA.

Type of Post: U/G; ORLIT 'A'; ORLIT 'B'; A/G Other;
Master: Recent/Past ; Non Master: ☐ Closure: 1992/Earlier/1968/Earlier

Post Status: Intact ☒ Partly demolished ☐ Removed ☐ Not found ☐

Site: Flat ☐ Mounded ☒ Slight ☒ Medium ☐ Heavily ☐ Steps/Paving
Shape: ☐ ☐ ☐ ☐ Large/medium/small

NO COMPOUND - IN SHEEP FIELD 25yds FROM ROAD. CONCRETE FENCE POSTS IN ROADSIDE

Surface/vegetation: HEDGE + 2 LARGE VERTICULAR FENCE POSTS AT LH VIEWED FROM ROAD

Fencing: None: ☒ Gates: 0,1,2 Style: STONE VERTICULAR GATEWAY POSTS

Entrance:

Condition of Post: BOLTED ON L13 - SURROUND BROKEN UP.
Entrance Turret UNPAINTED, SOUND. Hatch: SOUND BUT RMSTY Type X
Hatch hinged: 1-2, 2-3, 3-4, 4-1 Keyhole type: L K/H X cover
Steps: A ☐ B ☐ C ☒ none ☐ single/double, Not solid: ☐
Turret profile: square/chamfered (round/squared)
Ventilators: raised/flush, metal/wooden, No of slats: ☐ None: Y N
condition: STEP FALLING AWAY - NO VENTILATORS

Ventilator Turret
Top Type: Flat ☐ Domed ☐ Hipped ☒ Pitched A-C, B-D Square/oblong ON GROUND
Sloping A-C, C-A, B-D, D-B.

Ventilators: None ☐ Wooden ☐ Metal ☐ Box/flush ☐ No of Slats ☐

Surfaces: Painted UNPAINTED - BRICK BASE Crumbling/damage TOP ON GROUND - ELSE OK.

Security: Locks: 1 2 0 Hasps: 1 2 0 Locking Bar Y/N Lckng Bar Locations: Y/N
Master equipment: NONE

Details of A/G Post on site: NONE

Operational equipment on site: -

Non-standard features: FSM PIPE IN CONCRETE & TOP BOLTED
BPI PIPE VERY SHORT - IN CONCRETE

Post Personnel known:

