

Mountain Burial Chamber Works to Scheduled Monument Report

In the first two weeks of October the agreed works of re-fencing the eastern area of the scheduled area was completed. The work was undertaken by the land owner Mr Pat Waller which included removing the old fence posts and replacing them with new ones. The new fence posts were drive into the existing holes. Below, there are two images that show the completed work and two images of the fence line before the work was carried out.





