


Stephen L Thomas Llangain Designs


12 Dol Y Dderwen, Llangain, Carmarthen. SA33 5BE Tel: 01267 241759 Email: llangaindesigns@aol.com

Existing Photographic Survey of Existing Stables @

Garness Farm, Marros Pendine Carmarthenshire SA33 4PN



Architectural Survey & Planning Plans



Elevation Photos

South Elevation – Summer and Winter Views





East Elevation – Summer & Winter Views






North Elevation



Doors & Window Photos

South Elevation Stables Door – 1780m Wide x 2100m



South Elevation - Window 0.9m x 0.9m and blocked up doorway 1.0m x 2.0m and Arrow Slit 0.1m x 0.6m



South Elevation - Stable Door and Arrow Slit



South Elevation Roof light



Internal Photos

Looking Towards East Gable window 1.12m x 1.3m



Looking Towards East Gable



Internal View of Window 0.9m x 0.9m on South Elevation



Internal View of Window 0.9m x 0.9m on North Elevation



Internal Blocked up doorway Looking North



Roof Structure – Looking West



Photographic Record Undertaken on 22.06.2022



