

Photographic survey of the outbuilding at Frowen, Cefn Y Pant,
Whitland to discharge condition 3 from planning reference
PL/08298 Dated 5th January 2025




Front east elevation



Front Elevation as Existing

1:100


Rear west elevation



Rear Elevation as Existing


1:100

North (gable)elevation




Right-Side Elevation as Existing 1:100

South (gable) elevation



Left-Side Elevation as Existing 1:100

Internal ground floor



First floor




Image 1



Image 2



Image 3



Image 4



Image 5



Image 6



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12



Image 13



Image 14



Image 15



Image 16



Image 17



Image 18



Image 19



Image 20



Image 21



Image 22



Image 23

