

Photographic Survey of Existing Farm house / Dwelling and Adjacent Redundant Agricultural Outbuilding Earmarked for Demolition as Part of an Approved Scheme to Erect a Replacement Dwelling on This Site at -

Pantmoch Bach, Maesymeillion, Llandysul, Ceredigion. SA44 4NH.



Dwelling / Farm House



View of front & South side of farmhouse.



Front elevation – farm house – North-East facing



North-West facing side elevation of farm house



North-West facing side elevation of farm house



Part view of Rear of Farm house showing red brick addition – South-West facing



Rear view of Farm house – South-West facing



Showing rear addition in red facing brick off the rear of Farm house



South-West facing side elevation to farm house showing red brick rear addition



Rear / Side view of farm house



Internal image of rear red brick rear addition to main farm house



Living Room Fireplace – Farm house



Sitting Room fireplace – Farm house



Looking up staircase from Hall – Farm house



Looking towards rear window on landing – Farm house



Within bedroom 2 – Farm house



Within bedroom 1 – farm house



Within bedroom 1 – farm house



Overall photo of Farm house & Redundant Outbuilding - both to be demolished – East facing



South East facing / Front Elevation to outbuilding – part traditional part blockwork



North-East side facing elevation to outbuilding



Image showing rear ( North-West facing ) and side ( South-West facing ) to outbuilding.

Large, more recent blockwork addition to the rear.



South-West view of outbuilding



Front view South-East facing to outbuilding