

East facing gable end



Inside view of window in gable end facing east



South facing main entrance



Inside south facing main entrance



Inside, south facing windows




South-East facing corner showing external chimney



East facing gable end windowoutside




West facing gable end



Inside south facing window



North external wall and West facing gable end



East facing gable end showing external chimney



North facing external wall



Inside north facing wall



Inside west facing gable end



South facing main entrance



Fireplace on east facing gable end



Inside east facing gable end.


Fireplace to the right and window to the left of internal wall



South facing window to right of main entrance



Internal view of north facing wall



External view of south facing main entrance and windows



Internal view of window on east facing gable end



External view of window on east facing gable end