

No topographical survey has been undertaken and no levels are available.

No ground investigations have been undertaken.

All dimensions are in millimetres unless otherwise stated.

This drawing should not be scaled and any dimensions verified on site.

Imported Rock Source: All imported boulders must be sourced from a local accredited quarry, subject to approval by the Senior Engineer prior to the commencement of works.

Rock Placement: The exact location of the imported boulders is to be agreed upon on-site with the Engineer's representative.



Existing Conditions

Scale: 1:250

\Box	Amendments				1	Project	By DD	Checked OS	Scale at A3		
	Rev	Date	Description	Ву	Chkd	ED3843 Ystwyth Trail, Llanilar			As show	n	
: (Erosion Control	Date October 2024		This drawing should not be scaled. All dimensions are in millimetres unless otherwise stated		
						21001011 00114101	Project Number	Drawing Number		Revision	
IICE .uk F 5LG						Existing Conditions Plan	ED3843		01		
HR copyrights are							© Hawlfraint y Goron a hawliau cronfa dde © Crown copyright and database rights 20 REGISTRARS REGISTRARS OHSAS 18001	Drawing Filename	S .		