

Planning Application: A220770

Level 1 Photographic Survey

Cwmceirw, Llanfarian, Aberystwyth SY23 4QG

Survey Prepared and submitted by A O'Regan

Part 2 of 2

Contents

Planning Application: A220770.....	1
List Of Tables	2
List of Figures.....	2
List of Plates.....	3
1.0 INTRODUCTION.....	Error! Bookmark not defined.
1.1 LEVEL 1 PHOTOGRAPHIC SURVEY	Error! Bookmark not defined.
2.0 METHODOLOGY	Error! Bookmark not defined.
2.1 Written Account.....	Error! Bookmark not defined.
2.2 Drawing.....	Error! Bookmark not defined.
2.3 Photography	Error! Bookmark not defined.
3.0 BUILDINGS SURVEY.....	Error! Bookmark not defined.
3.1 Precise Location of the Buildings	Error! Bookmark not defined.
3.2 Drawing.....	Error! Bookmark not defined.
3.3 Photography	4
3.3.1 Location Setting	4
3.3.2 Building A Photographs	5
3.3.3 Building B Photographs.....	6
3.3.4 Building C Photographs.....	11
4.0 Summary.....	14
End.....	14

List Of Tables

Table 1: Compass point building locations.....	Error! Bookmark not defined.
--	------------------------------

List of Figures

Figure 1: Site location	Error! Bookmark not defined.
Figure 2: Buildings plan locations	Error! Bookmark not defined.
Figure 3: Building A Internal Plan and External Elevations.....	Error! Bookmark not defined.
Figure 4: Building B External Elevations	Error! Bookmark not defined.
Figure 5: Building B Internal Plan	Error! Bookmark not defined.
Figure 6: Building C External Elevations	Error! Bookmark not defined.
Figure 7: Building C Internal Plans	Error! Bookmark not defined.

List of Plates

Plate 1: Buildings A, B and C South Elevation	4
Plate 2: Buildings B and C South Elevation	4
Plate 3: Buildings A and B North Elevation	4
Plate 4: Building A East and North Elevation	5
Plate 5: Building A West and South Elevation.....	5
Plate 6: Building A Internal Construction.....	5
Plate 7: Building B East and North Elevations.....	6
Plate 8: Building B Eastern Elevation	6
Plate 9: Building B South Elevation.....	6
Plate 10: Building B West Elevation	6
Plate 11: Building B Ventilation Slit Central Section South Elevation	6
Plate 12: Building B Ventilation Slit West Section South Elevation.....	6
Plate 13: Building B South Elevation -Door into West Section	6
Plate 14: Building B West Elevation -Ground Floor Ventilation Slits.....	7
Plate 15: Building B West Elevation -Top Ventilation Slits	7
Plate 16: Building B North Elevation.....	7
Plate 17: Building B East Section Ground Floor North Elevation	7
Plate 18: Building B East Section Ground Floor Internal Stone Work.....	7
Plate 19: Building B North Elevation -Central Section Access.....	7
Plate 20: Building B Central Section -Ventilation Opening to West Section	8
Plate 21: Building B Central Section -Internal Access from North	8
Plate 22: Building B Central Section -Roof Construction	8
Plate 23: Building B Central Section -First Floor Access from South.....	8
Plate 24: Building B North Elevation -Door into West Section	8
Plate 25: Building B West Section -Internal West Elevation	8
Plate 26: Building B West Section -Internal Wall with Central Section.....	9
Plate 27: Building B West Section -Roof Construction.....	9
Plate 28: Building B North Elevation -Ventilation Slit West Section	9
Plate 29: Building B West Section -Ground Floor Ventilation Slit to North	9
Plate 30: Building B Eastern Elevation	9
Plate 31: Building B Eastern Section Entrance Door	9
Plate 32: Building B Eastern Section Roof Construction	10
Plate 33: Building B Eastern Section -Internal Layout.....	10
Plate 34: Building B Ventilation Opening into Central Section	10
Plate 35: Building C South Elevation.....	11
Plate 36: Building C East Section South Elevation	11
Plate 37: Building C East Section Ground Floor Internal Layout	11
Plate 38: Building C West Section South Elevation.....	11
Plate 39: Building C West Section -Raised Door South Elevation	11
Plate 40: Building C West Section Internal Layout.....	11
Plate 41: Building C West Section -Access from North	12
Plate 42: Building C West Section -Roof Construction.....	12
Plate 43: Building C West Section -Internal Stonework.....	12
Plate 44: Building C West Section -Ventilation Stonework	12
Plate 45: Building C West Section -Ventilation Slit to North.....	12
Plate 46: Building c West Section -Ventilation opening Western Elevation	12
Plate 47: Building C East Elevation.....	13
Plate 48: Building C East Elevation Brickwork.....	13
Plate 49: Building C East and North Elevations.....	13
Plate 50: Building C Ventilation Opening North Elevation	13
Plate 51: Building C Ventilation Slit on North Elevation	13
Plate 52: Building C West Elevation	13
Plate 53: Building C Ventilation Opening West Elevation	13

3.3 Photography

The following photographys are listed and presented in the the order of 1.Location setting, 2.Building A, 3.Building B and then 4.Building C. The accompanying files use the same digital photo names and titles as below.

3.3.1 Location Setting

Plate 1: Buildings A, B and C South Elevation



Plate 2: Buildings B and C South Elevation



Plate 3: Buildings A and B North Elevation



3.3.2 Building A Photographs

Plate 4: Building A East and North Elevation



Plate 5: Building A West and South Elevation



Plate 6: Building A Internal Construction



3.3.3 Building B Photographs

Plate 7: Building B East and North Elevations



Plate 8: Building B Eastern Elevation



Plate 9: Building B South Elevation



Plate 10: Building B West Elevation



Plate 11: Building B Ventilation Slit Central Section South Elevation



Plate 12: Building B Ventilation Slit West Section South Elevation



Plate 13: Building B South Elevation -Door into West Section



Plate 14: Building B West Elevation -Ground Floor Ventilation Slits



Plate 15: Building B West Elevation -Top Ventilation Slits



Plate 16: Building B North Elevation



Plate 17: Building B East Section Ground Floor North Elevation



Plate 18: Building B East Section Ground Floor Internal Stone Work



Plate 19: Building B North Elevation -Central Section Access



Plate 20: Building B Central Section -Ventilation Opening to West Section



Plate 21: Building B Central Section -Internal Access from North



Plate 22: Building B Central Section -Roof Construction



Plate 23: Building B Central Section -First Floor Access from South



Plate 24: Building B North Elevation -Door into West Section




Plate 25: Building B West Section -Internal West Elevation



Plate 26: Building B West Section -Internal Wall with Central Section



Plate 27: Building B West Section -Roof Construction



Plate 28: Building B North Elevation -Ventilation Slit West Section



Plate 29: Building B West Section -Ground Floor Ventilation Slit to North



Plate 30: Building B Eastern Elevation



Plate 31: Building B Eastern Section Entrance Door



Plate 32: Building B Eastern Section Roof Construction



Plate 33: Building B Eastern Section -Internal Layout



Plate 34: Building B Ventilation Opening into Central Section



3.3.4 Building C Photographs

Plate 35: Building C South Elevation



Plate 36: Building C East Section South Elevation



Plate 37: Building C East Section Ground Floor Internal Layout



Plate 38: Building C West Section South Elevation



Plate 39: Building C West Section -Raised Door South Elevation



Plate 40: Building C West Section Internal Layout



Plate 41: Building C West Section -Access from North



Plate 42: Building C West Section -Roof Construction



Plate 43: Building C West Section -Internal Stonework



Plate 44: Building C West Section -Ventilation Stonework



Plate 45: Building C West Section -Ventilation Slit to North



Plate 46: Building c West Section -Ventilation opening Western Elevation



Plate 47: Building C East Elevation



Plate 48: Building C East Elevation Brickwork



Plate 49: Building C East and North Elevations



Plate 50: Building C Ventilation Opening North Elevation



Plate 51: Building C Ventilation Slit on North Elevation



Plate 52: Building C West Elevation




Plate 53: Building C Ventilation Opening West Elevation



4.0 Summary

The information and photographs presented within this report provide an accurate record of the subject buildings.

This survey adheres to the guidance afforded by Dyfed Archaeological Trust- Heritage Management and is considered an appropriate assessment.

End