

41445 MON (former Valley Rural District)

LANDRYGARN, Windmill (former)

SCOFFORD

S1/25/5

Not. Grid: 390801 Ref: 16/5 (sq. 25)

II 18C circular wall of windmill remains in good upwards. 3 stages above vertical base plinth. Mortared rubble masonry. Rectangular windows at each floor, with roughly dressed voussoirs at heads, now filled in with sheepskin. Ground floor doorways have slightly cambered heads. Internals used as shoppin:

R.C.A.M. p dxiii