

YNYS MON

LIANGRISTIDLOS, rubble, to north, St Hen Blas

1/49/11



Dec 1978

Not Grid 422725 Ref: 40/11

- II Day 18C, 2 storeys including loft approached by external stairs. Rubble masonry with large stones at angles. Rest of old small slates. 3 wide doorways, at ground floor, south, with segmental arches. Flat headed 1st-floor windows, with voussoirs. Circular windows in end gables and in centre gable, north, filled in.