18

10

95



Site Notes/List or Scheduling Description

Canal arm and limekilns. EC19. Coursed rubble sandstone. Canal arm extends to wharf, formerly for the movement of coal and limestone. Limekilns set in embankment, three bays of two openings, with protruding terminating piers. Round arched recesses with dressed stone voussoirs and prominent keystones, beneath string course. Rubble stone piled to the back of opening. Now overgrown and derelict.

				4		
		.;				
		<del>-,</del>			÷	
				• • •	• • • • •	
-						
					• •	
		****				
	#				,	
				-		
	- · · · · · -			-		
			· · · · · · · · · · · · · · · · · · ·			
÷			<u></u>			

G Defects

Repairs





