

## BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

140

A	BW Region	M+SW	PRN	
	Waterway	M+BC	OS Sheet	
	BW Struc No		NGR	
	Side	TOW <input checked="" type="radio"/> OFF <input type="radio"/> CEN <input type="radio"/> OTH	Photo Neg No	11/6+7
	BW Owned	<input checked="" type="radio"/> Y <input type="radio"/> U/K <input type="radio"/> N	MMS/PMS	

B	County	GWENT	Alt Address	
	LA District	Monmouth		
	Parish			
	Address	STOP GATES AT		

C	Date Listed				SAM No	
	Grade	I	II*	II	Protected Area	<input checked="" type="radio"/> NP <input type="radio"/> AONB <input type="radio"/> CA <input type="radio"/> SSSI
	Serial No				Structures in Item	

D	Design Integ	A	B	<input checked="" type="radio"/> C	D	Context	VIL	URB	<input checked="" type="radio"/> ISO	GRO
	Setting	A	<input checked="" type="radio"/> B	C	D	Condition	A	B	<input checked="" type="radio"/> C	D
	Group Value	Y	<input checked="" type="radio"/> N			Present Use	DISUSED			
	Listable	Y	<input checked="" type="radio"/> N							

E	Building Type	STOP GATES								
	Date	1)		2)		3)	1 (20			
	Designer(s)									
	Materials	BR	ST	EBR	CO	IR	ME	<input checked="" type="radio"/> WD		
		TI	SL	CTI	CER	AS	OTH			

S Features/  
Tech Merit

Date Inspected 17 10 95

---

F Site Notes/List or Scheduling Description

Set of two stopgates. LC20, replacing gates of earlier origin. Wooden gates set in stone recesses. Disused, with very occasional usage.

---

G Defects

Repairs

---



MB140 11/06



MB140 11/07