

BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB.

A	BW Region	M + SW	PRN	206
	Waterway	M + BC	OS Sheet	
	BW Struc No		NGR	
	Side	TOW OFF <u>CEN</u> OTH	Photo Neg No	14/35 - 36; 15/11
	BW Owned	<u>Y</u> U/K N	MMS/PMS	
B	County	GWENT	Alt Address	
	LA District	Torfaen		
	Parish			
	Address	PONTYMOILE AQUEDUCT		
C	Date Listed		SAM No	
	Grade	I II* II	Protected Area	NP AONB CA SSSI
	Serial No		Structures in Item	
D	Design Integ	A <u>B</u> - <u>C</u> D	Context	VIL <u>URB</u> ISO GRO
	Setting	A <u>B</u> C D	Condition	A <u>B</u> - <u>C</u> D
	Group Value	Y <u>N</u>	Present Use	AQUEDUCT
	Listable	Y ? N		
E	Building Type	AQUEDUCT		
	Date	1) 1812 2)		3) C19 + C20 REBUILDING
	Designer(s)	WILLIAM CROSSLEY		
	Materials	<u>BR</u> <u>ST</u> EBR <u>CO</u> IR ME WD		
		TI SL CTI CER AS OTH		
	S Features/ Tech Merit			
	Date Inspected	28 10 95		

F Site Notes/List or Scheduling Description

Aqueduct. c1812 with C19 and C20 renewal. Coursed rubble sandstone. Elliptical arch with dressed stone voussoirs and prominent keystones. Curved parapet wall to towpath, rebuilt and patched with cement. Flat stone copings, replaced with brick to the offside. North of the aqueduct is concrete overflow wier taking water from the canal for industrial purposes at nearby factory.

G Defects

Repairs



MB206

14/35



MB206 14/30



MB206 15/01