

## BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

A	BW Region	M+SW	PRN	137
	Waterway	M+BC	OS Sheet	SO 2717 1367
	BW Struc No	BR. NO. 97	NGR	
	Side	TOW OFF <input checked="" type="radio"/> CEN OTH	Photo Neg No	11/12-14
	BW Owned	<input checked="" type="radio"/> Y <input type="radio"/> N/K N	MMS/PMS	
B	County	GWENT	Alt Address	GRIVILON YARD BR.
	LA District	Monmouth		
	Parish			
	Address	BR 97, TAKING B4246		
C	Date Listed		SAM No	
	Grade	I II* <input checked="" type="radio"/> II	Protected Area	<input checked="" type="radio"/> NP AONB CA SSSI
	Serial No	33/C/45(2)	Structures in Item	
D	Design Integ	A <input checked="" type="radio"/> B C D	Context	VIL URB ISO <input checked="" type="radio"/> GRO
	Setting	A <input checked="" type="radio"/> B C D	Condition	A <input checked="" type="radio"/> B C D
	Group Value	<input checked="" type="radio"/> Y N	Present Use	PUBLIC ROAD BRIDGE
	Listable	<input type="radio"/> Y <input checked="" type="radio"/> N		
E	Building Type	PUBLIC ROAD BRIDGE		
	Date	1) 1812 2)		3) WIDENED, REPAIRED (20
	Designer(s)	WILLIAM CROSSLEY (ENG.)		
	Materials	BR <input checked="" type="radio"/> ST EBR <input checked="" type="radio"/> CO IR ME WD		
		TI SL CTI CER AS OTH		
	S Features/ Tech Merit			
	Date Inspected	17 10 95		

---

F Site Notes/List or Scheduling Description

- Public road bridge. c1812, widened and repaired C20. William Crossley engineer. Coursed dressed rubble sandstone. Elliptical arch with stone voussoirs and flat stone copings, patched with concrete in places. Bridge soffit heavily jointed with mortar. Northern wingwall sweeps down to path on towside. Terminating piers to offside, patched with rubble stone. Reconstituted stone steps on towside up to road level.

---

G Defects

Repairs

---



MB137 11/12



MB137 11/13





MB137

11/14