

BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

A	BW Region	M + SW	PRN	147
	Waterway	M + BC	OS Sheet	50 2945 1153
	BW Struc No	BR NO 93	NGR	
	Side	TOW OFF <u>CEN</u> OTH	Photo Neg No	101 28 + 30
	BW Owned	<u>Y</u> U/K N	MMS/PMS	
B	County	GWENT	Alt Address	RICHARD'S FARM BR.
	LA District	Monmouth		
	Parish			
	Address	BR NO 93 ADJACENT TO BRIDGE FARM		
C	Date Listed		SAM No	
	Grade	I II* <u>II</u>	Protected Area	<u>NP</u> AONB CA SSSI
	Serial No	33/C/53+54(2)	Structures in Item	
D	Design Integ	A <u>B</u> C D	Context	VIL URB ISO <u>GRO</u>
	Setting	A <u>B</u> C D	Condition	A <u>B</u> C D
	Group Value	Y <u>N</u>	Present Use	ACCESS RD BRIDGE
	Listable	Y ? <u>N</u>		
E	Building Type	ACCESS ROAD BRIDGE		
	Date	1) 1812 2)		3) C19+C20 ALTERATIONS
	Designer(s)	WILLIAM CROSSLEY		
	Materials	BR <u>ST</u> EBR CO IR ME WD		
		TI SL CTI CER AS OTH		
	S Features/ Tech Merit			
	Date Inspected	17 10 95		

F Site Notes/List or Scheduling Description

Access road bridge. c1812 with C19 and C20 alterations. William Crossley engineer. Coursed dressed rubble sandstone. Elliptical arch with dressed stone voussoirs and protruding keystones. Flat rubble stone copings. Terminating piers rebuilt on towside, replaced with buttress to southern elevation.

G Defects

Repairs



MB147 10/28

