

BRITISH WATERWAYS ARCHITECTURAL HERITAGE SURVEY

MB

A	BW Region	M + S W	PRN	159
	Waterway	M + BC	OS Sheet	
	BW Struc No	BR NO: 85	NGR	
	Side	TOW OFF <input checked="" type="radio"/> CEN OTH	Photo Neg No	1015 + 7
	BW Owned	<input checked="" type="radio"/> Y U/K N	MMS/PMS	
B	County	GWENT	Alt Address	
	LA District	Mammoth Torfaen		
	Parish			
	Address	BR NO. 85, THIMBLES BRIDGE		
C	Date Listed		SAM No	
	Grade	I II* II	Protected Area	<input checked="" type="radio"/> NP AONB CA SSSI
	Serial No		Structures in Item	
D	Design Integ	A <input checked="" type="radio"/> B C D	Context	VIL URB <input checked="" type="radio"/> ISO GRO
	Setting	A <input checked="" type="radio"/> B C D	Condition	A <input checked="" type="radio"/> B C D
	Group Value	Y <input checked="" type="radio"/> N	Present Use	FOOTBRIDGE / FARM TRACK
	Listable	Y <input checked="" type="radio"/> N		
E	Building Type	ACCOMMODATION BRIDGE		
	Date	1) 1812 2)		3) CIA + C20 RENEWAL
	Designer(s)			
	Materials	BR <input checked="" type="radio"/> ST EBR CO IR ME WD		
		TI SL CTI CER AS OTH		
	S Features/ Tech Merit			
	Date Inspected	17 10 95		

F Site Notes/List or Scheduling Description


Accommodation bridge, slightly skew to canal. c1812 with C19 and C20 renewal. William Crossley engineer. Coursed rubble sandstone, patched and replaced in places. Elliptical arch with dressed stone voussoirs and prominent keystones. Hump-backed parapet, battered to the western elevation with flat stone copings. Protruding terminating piers.

G Defects

Repairs



MB159 10/05





MB159 10/07