•	BRITISH WA	M+SW	<u></u>			1//			
A	BW Region				PRN	166			
	Waterway	M+BC			OS Sheet				
	BW Struc No	BR NO BI			NGR				
	Side	TOW OFF	CEN) отн	Photo Neg No	0 12 / 10 + 11			
	BW Owned	Y	(UK)	N	MMS/PMS				
в	County	GWENT			Alt Address	LLANOVER BRIDGE			
	LA District Parish Address	Monumora BR No. 8	HADT T	Torfaen	- BÁD MOVSE	·····			
	Date Listed		(j~v3~		SAM No	-			
	Grade	· · · · · · · · · · · · · · · · · · ·	*	11	Protected Are	a (NP) AONB CA SSSI			
	Serial No				Structures in Item				
)	Design Integ	A B	С	D	Context	VIL URB ISO GRO			
	Setting	A B	С	D	Condition	A (B) - (C) D			
	Group Value	Y	(N)	····	Present Use	ROAD BRIDGE			
	Listable	- Y	(\mathbb{N})		·				
Ε	Building Type PUBLIC RUAD BRIDGE								
	Date	1) 1812		2)		3) CIQ + CZO RENEWAL/			
	_ Designer(s)	WILLIAM	n cri	JSLEY		REBUILDING			
	Materials	BR (ST)_	EBR					
		TI	SL	СТІ	CER	AS OTH			
	S Features/ Tech Merit								
	Date Inspected	18	10 ¹	95	· · · ·	· · · · · · · · · · · ·			

F Site Notes/List or Scheduling Description

Public road bridge. c1812 with C19 and C20 renewal. William Crossley engineer. Coursed rubble sandstone. Segmental arch has been rebuilt with engineering brick voussoirs and soffit, and reconstituted stone beneath springing line. Slightly hump-backed parapet with engineering brick copings. Plastic pipe carried on MC20 rubble stone abutments just south of the bridge.

			,		
					-
	···· ·· ·· ··· ···	··· ··· ·· ·· ··			
·					
		. .	· · · ·		
	••••				
					,
	• · · · • • •				
	• • • • •				
			.		
	· · · · ·			-	\bullet
• -			• • • • • • • • • • • • • • • • • • • •		

G Defects

Repairs



